NUMBER OF COPIES RE	CEIVED			·		·			EODH C 120	
DISTRIBUTION			IEW MEXICO OIL CONSERVATION MMISSION FORM C-128 Revised 5/1/57 WELL LOCATION AND ACREAGE DEDICATION PLAT							
SANTA FE FILE										
U.S.G.S.										
	IAS		SEE INSTR	UCTIONS FO	OR COMPL	ETING TH	IS FORM ON	THE REVI	ERSE SIDE	
PRORATION OFFICE										
OPERATOR					CTION	_	1992 (NL 33	71 3 15	
0					ECTION ease	^			Well No.	
Operator Sulf Oil Corporation						eonard (hct-f)		l l	
Unit Letter Section			Township		Range		County			
¥		2	21-5		37-	<u> </u>	<u>I</u> A	4		
Actual Footag			3				, .	D	1:	
860		t from the		line and	198	O fe	et from the	Best	line	
Ground Level Elev.		Producing Formation		F	Pool Drinkard				Dedicated Acreage: Acres	
3487'		1	Drinkard						. ("Owner" means the person	
another. 2. If the answ wise? YES	(65-3-29 ver to que S	9 (e) NMSA 1: estion one is NO	935 Comp.) "no," have the If answer is "ye	interests of es," Type of	all the ov f Consolid	vners been	consolidated	by commun	mself or for himself and	
w	ver to que	estion two is	"no," list all t	he owners ar				· · · · · · · · · · · · · · · · · · ·		
Owner					I	and Descri	ption			
			SECTIO	N B					CERTIFICATION	
						<u></u>		in SECT plete to belief.	recertify that the information TON A above is true and comthe best of my knowledge and Activities.	
					1			Position	Production Manager	
								Compan		
		! !						Date July	30, 1962	
								shown o	certify that the well location on the plat in SECTION B was from field notes of actual	
								surveys supervi	made by me or under my sion, and that the same is true tect to the best of my knowledg	
				•)			Date Su	rveyed	
									red Professional Engineer Land Surveyor	

330 660 990 1320 1650 1980 2310 2640

Certificate No.

INSTRUCTIONS FOR COMPLETION OF FORM C-128

- 1. Operator shall furnish and certify to the information called for in Section A.
- 2. Operator shall outline the dedicated acreage for both oil and gas wells on the plat in Section B.
- 3. A registered professional engineer or land surveyor registered in the State of New Mexico or approved by the Commission shall show on the plat the location of the well and certify this information in the space provided.
- 4. All distances shown on the plat must be from the outer boundaries of the Section.
- 5. If additional space is needed for listing owners and their respective interests as required in question 3 of Section A, please use space below.

NUMBER OF COPIES RECEIVED							
DISTRIBUTION							
SANTA FE		T					
FILE							
U. S. G. S.	1						
LAND OFFICE							
	OIL						
TRANSPORTER	GAS						
PRORATION OFFI	CE	1					
OBERATOR							

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico Santa Fe, New Mexico

MISCELLANEOUS NOTICES 11 3 32

r agent, of the plan submitted. The plan on a instructions in the Rules and Re	e given the approval, with any modification an as approved should be followed, and we	ission, before the work specified is to begin. A copy will be ns considered advisable, or the rejection by the Commission ork should not begin until approval is obtained. See addi-		
Onal histractions in the states and the	Indicate Nature of Notice by Che	cking Below		
OTICE OF INTENTION O CHANGE PLANS	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper		
TOTICE OF INTENTION O PLUG WELL	Notice of Intention to Plug Back	Notice of Intention to Set Liner		
Totice of Intention o Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)		
Ortice of Intention o Gun Perforate	Notice of Intention (Other)	Notice of Intention (Other) Abandon Wants abo &		
OIL CONSERVATION COMMISSIO	ON Hobbs, Net	Recomplete in Drinkard w Mexico June 22, 1962		
SANTA FE, NEW MEXICO	(Place)	(Date)		
Gentlemen: Following is a Notice of Intention	to do certain work as described below at	the		
Gulf Oil Corporation (Company or O	Herry Leonard (NCT-F)	Well No. in (Unit)		
(40-acre Subdivision)				
1. Pall rods, pump 2. Set CI BP on Win 3. Load hole with I 4. Selectively perf by Geologist. 5. Run 3-1/2" frec 6. Spot and squeese with 24,000 gale in 6 equal stage 7. Swab and test. 8. Kill well with I	add tubing. The Line At 6900'. Dump 2 sales oil. Pressure test can come to Brinkard pay in the 1 tubing with retr. BP and Fine 500 gals 15% NE Acid into 2 2 gyty refined oil contains. Stage treatment using Finese oil them pull free tubing for production string and	sing and BP with 1000%. nterval 6698-6772 as directed pakker. formation, then frac treat ning 1/40# Adomite M-11 & 3# SPO ENB sealers. sing and straddle tools.		
Approved OIL CONSERVATION COMMISSI	Position	Area Production Manager Send Communications regarding well to:		
By Leslie & Cle	Name Name			
Title	Address	Box 2167, Hobbs, New Mexico		