STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	-	
SANTA FE		
FILE		
U.1.G.E.		
LAND OFFICE		
OPERATOR		

CONDITIONS OF APPROVAL, IF ANY

OIL CONSERVATION DIVISION

DISTRIBUTIO	1. 5. 50 × 2088	Form C-103
FILE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78
U.S.O.S.		Sa. Indicate Type of Lease
LAND OFFICE		State X Fee
PERATOR		5. State Oti & Gas Lease No.
•		
	SUNDRY NOTICES AND REPORTS ON WELLS	
[DO MOT USE THI	S FORM FOR PREPENSALS TO DRILLION TO DEEPEN OR PLUE BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
Eir X	WELL OTHER-	
2. Name of Operator		8. Farm or Lease Hame
SHELL WESTERN	F&P INC.	STATE SECTION 2
J. Address of Operator	21101	9. Well No.
P. O. BOX 991	, HOUSTON, TEXAS 77001 .	7
4. Location of Well	,	10. Field and Pool, or Wildert
	V 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM	WANTZ ABO
UNIT LETTER	FEET FROM THE SOUTH LINE AND 1500 FEET FROM	WALLS ADD
WEST	LINE, SECTION 2 TOWNSHIP 21-S RANGE 37-E NUPM.	
THE	LINE, SECTION TOWNSHIP RANGE NMPM.	
THITTINITY	15. Elevation (Show whether DF, RT, GR, esc.)	12. County
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	LEA AMMINISTRA
16.	Check Appropriate Box To Indiana November 1 November 1	
·	Check Appropriate Box To Indicate Nature of Notice, Report or Other	
. NC	SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORL	PLUC AND ABANDON REMEDIAL WORK	
		ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING DENS.	PLUG AND ABANDONERT
PULL OR ALTER CABING	CMANGE PLANS CASING TEST AND COMENT JOB CONTESTED DI TNEDDY	DOINVADD DECOM EV
	OTHER SOUEEZED BLINEBRY OF PLETED IN WANTZ ABO	
OTHER	TELTED IN WARTE ADV	D, ACID TRAC D
17. Describe Proposed o	or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including e	stimated date of starting any proposed
work) SEE RULE II		
5-13-85: Pu	lled production equipment.	
E 14 OF . C1.		
5-14-85: Cle	eaned out to 6762'.	•
E 15 05. Co.	t a omt motainen A 6/001: Causand Buildead asufic /67771	(7251) (100 07
5-15-85: Set	t a cmt retainer @ 6482'. Squeezed Drinkard perf's (6577'	- 6/35') W/100 sx Class
ا م	" cmt w/.3% Halad-9 followed by 100 sx Class "C" w/2% CaCl2	Set a cmt retainer
: بى ئەرا	5539'. Squeezed Blinebry perf's (5631' - 5898') w/100 sx C	lass "C" cmt w/.3%
Па	lad-9 followed by 150 sx Class "C" cmt $w/2\%$ CaCl ₂ . WOC 24 l	irs.
E 16 +0 E 10	OF. Dwilled out ant waterman A FF201 and dwilled it.	, F0001 B
2-10 (0 2-10-	-85: Drilled out cmt retainer @ 5539' and drilled thru cmt	to 5900 Pressure
LE:	sted Blinebry squeeze to 750 psi, held OK. Drilled out cmt	retainer @ 6482 and
מו	illed thru cmt to 6739'. Pressure tested Drinkard squeeze	to 750 ps1, held UK.
CIE	eaned out to 6850'.	
5-20-85: Kno	noked out CIRD & FOEO! alcomed out to 7520! Cot - CIRD O	74501 1 /251
3-20-63: KNC	ocked out CIBP @ 6850', cleaned out to 7538'. Set a CIBP @ t (PBTD = 7415').	7450', capped w/35'
Cin	((FBID = 7415).	
5 21 95 · Dov	rforated Wantz Abo from 7014' - 7349' (1 JSPF, 68 holes).	
J-21-6J. Fei	riorated wantz Abo from 7014 - 7349 (1 03PF, 08 hores).	
	(CONTINUED ON REVERSE SIDE)	
18. I hereby cently that	the information above is true and complete to the best of my knowledge and belief.	
4/1		
(//////////////////////////////////////	A. J. FORE SUPERVISOR REG. & PERMITTING	PATE JUNE 6, 1985
The state of the s		
ORIGHNA	L SIGNED BY JERRY SEXTON	JUN 1 1 1985
Di	ISTRICT I SUPERVISOR	JOIN T I 1000

5-22-85: Acidized Wantz Abo 7014' - 7349' w/5000 gals 15% HCl-NEA.

5-23-85: Acid frac'd Wantz Abo 7014' - 7349' w/33,000 gals 20% Titan XL Acid/5 w/30% CO $_2$ + 46 ball sealers. Commenced flow testing well.

5-31 to 6-01-85: Installed production equipment (pump) and returned well to production.

JUN 10 1985

Form C-102 Supersedes C-128 Effective 1-1-65

NEW .EXICO OIL CONSERVATION COMMISSION WELL LOCATION AND ACREAGE DEDICATION PLAT

All distances must be from the outer boundaries of the Section Operator Lease Well No. WESTERN E&P INC STATE SECTION 2 Unit Letter Section Township Range 21-S 37-E LEA Actual Footage Location of Well: SOUTH feet from the 1980 line and feet from the WEST Ground Level Elev. Producing Formation Dedicated Acreage: 3473' DF WANTZ ABO WANTZ ABO Acres 1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below. 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling. etc? If answer is "yes," type of consolidation __ □No If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.). No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commis-L CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief. P J. FORE N SUPERVISOR REG. & PERMITTING SHELL WESTERN E&P INC. MAY 31, 1985 S T! R 0 I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief. U χ Date Surveyed 1980' Registered Professional Engineer and/or Land Surveyor Certificate No.

1650

1980

2000

RECEIVED

JUN - 8 1985 HOBBS OFFICE

DISTRIBUTION SANTA FE FICE U.S.G.S.

OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

	LAND OFFICE	REQUEST FOR				
	OPERATION	AND ANTIQUITATION TO TRANSPORT OF AND NATURAL CAS			÷	
1.	PADRATION OFFICE					
	SHELL WESTERN E&P	INC.				
	P. O. BOX 991, HO	USTON, TEXAS 77001			·	
	Reason(s) for filing (Check proper box)	Change in Transporter of:	Other (Please expl	-	ABLE OF 1440	RRI S
	Recompletion	Oil Dry Car				DDES
	Change in Ownership	Casinghead Gas Conden	sate		····	
	If change of ownership give name and address of previous owner					
11.	DESCRIPTION OF WELL AND I	EASF. Well No. Pool Name, Including Fo	. King	i of Lease	·	Lease No
	STATE SECTION 2	7 WANTZ ABO		. XXXXX	XXXXX	
	Location					
	Unit Letter V: 66	O Feet From The SOUTH Line				
	Line of Section 2 T. W	nahip 21-5 Range	37-Е . ММРМ.		LEA	County
n.	DESIGNATION OF TRANSPORT	ER OF OIL AND NATURAL GA	S Address (Give address to wh	ich approve	d copy of this form is	to be sent)
	SHELL PIPE LINE CORP.		P. O. BOX 1910, M	IDLAND,	TEXAS 79701	
	Name of Authorized Transporter of Cas	inghead Gas X or Dry Gas	Address (Give address to wh			
	TEXACO INC.	Unit Sec. Twp. Rge.	P. O. BOX 1137, E	When	NEW MEXICO 60	231
	If well produces oil or liquids, give location of tanks.	V 2 21-S 37-E	YES	i .	5-23-85	
	If this production is commingled wit	h that from any other lease or pool,	give commingling order num	nber:		
₹.	COMPLETION DATA	Oil Well Gas Well	New Well Workover D	eepen I	Plug Back Same Re	s'v. Diff. Res
	Designate Type of Completion		Total Depth		P.B.T.D.	
	Date Spudded	Date Compl. Ready to Prod.	Total Boyin			
	Everations (DF, RKB, RT, GR, etc.)	Name of Producing Formation	Top Oil/Gas Pay		Tubing Depth	
	Perforations				Depth Casing Shoe	
		TUBING, CASING, AND	CEMENTING RECORD			
	HOLE SIZE	CASING & TUBING SIZE	DEPTH SET		SACKS CE	MENT
			fter recovery of total volume o	of load oil a	nd must be squal to or	exceed top allo
	TEST DATA AND REQUEST FO	OR ALLOWABLE (Test must be a) able for this de	pth or be for full 24 hours)			
	Date First New Oil Run To Tanks	Date of Test	Producing Method (Flow, pu	mp, gas tijt	, 216.)	
	Length of Test	Tubing Pressure	Casing Pressure		Choke Size	
	Actual Prod. During Test	Oil-Bble.	Water-Bbis.		Gas - MCF	
	Actual From Dailing V					<u>,, </u>
	GAS WELL Actual Prod. Test-MCF/D	Length of Test	Bbis. Condensate/MMCF		Gravity of Condensat	t ●
	Testing Method (pitot, back pr.)	Tubing Pressure (Shut-in)	Casing Pressure (Shut-in)	Choke Size	
				SERVAT	ION DIVISION	
i	CERTIFICATE OF COMPLIAN		APPROVED	JUN -	3 1985	. 19
	I hereby certify that the rules and the Division have been complied with		ODIONA	L SIGNED.	BY JERRY SEXTON	L
	Division have been complete with any knowledge and belief.		DI		SUPERVISOR	
	•		TITLE	and In a	omollance with EUI	E 1194.
	A. J. FORE (Signature)		This form is to be filed in compliance with RULE 1104. If this is a request for allowable for a newly drilled or deepen			
			well, this form must be accompanied by a tabulation of the well in accordance with MULE 111.			
SUPERVISOR REG. & PERMITTING		All sections of this form must be filled out completely for allo				
	(Tule) · MAY 31, 1985		Fitt out only Sections I. II. III, and VI for changes of own- well name or number, or transporter, or other such Change of condition			
		1300	Separate Forms C	(1=11=1/01/	be filed for such	-
	•		I enmoleted wells.			

RECEIVED

JUN - 3 1985

HOBUS CHARE

STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	Ì	
DISTRIBUTION	7	Ī
BANTA FE		1
FILE		1
U.S.G.S.	T	
LANG OFFICE		
OPERATOR	T	

CONDITIONS OF APPROVAL, IF ANTI

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

SANTA FE, NEW MEXICO 87501	Revised 19-1-7
V.S.G.S.	Sa. Indicate Type of Lease
LAND OFFICE	State X Fee
OPERATOR	5. State Oii & Gas Lease No.
SUMPRY MOTICES AND DEPORTS OF WELL	XIIIIIIIIIIIII
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL-ON TO DEEPEN OR PLUC SACE TO A DIFFERENT RESERVOIR. 100 HOT USE THIS FORM FOR PROPOSALS.)	
	7. Unit Agreement Name
Z. Nome of Operator	
	8. Fam or Lease Hame
SHELL WESTERN E&P INC. 3. Address of Operator	STATE SECTION 2
P. O. BOX 991, HOUSTON, TEXAS 77001	7
4. Location of Well	DRINKARD Pool, or Wilder
UNIT LETTER V . 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM	BLINEBRY OIL & GAS
WEST 2 21.5 27.5	
THE WEST LINE, SECTION 2 TOWNSHIP 21-S RANGE 37-E HAPPY	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
1)	LEA ()
Check Appropriate Box To Indicate Nature of Notice, Report or Oti	her Data
NOTICE OF INTENTION TO: SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	
TEMPOPARILY ABANDON COMMENCE DRILLING OFMS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMENT JOB	
SOURETE DI INEDDY & DRINKARD DECOMPLETE ST	
IN WANTZ ABO, ACID FRAC	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.	estimated date of starting any proposed
1. Clean out to PBTD (CIBP @ 6850').	
 Set a cmt retainer @ ±6500'. Squeeze Drinkard w/100 sx Class "C" cmt + .3% Halad-9 followed by 1 	00 av 61aaa 6 amt 1
2% CaCl ₂ . (Drinkard perf's 6577' - 6735'.) WOC 24 hrs.	OU SX CIASS C CIIL +
4. Set a cmt retainer @ ±5550'.	
5. Squeeze Blinebry perf's 5631' - 5898' w/200 sx Class "C" cmt + .3%	Halad-9 followed by
200 sx Class "C" cmt + 2% CaCl2. WOC 24 hrs. 6. Drill out cmt. Pressure test squeezes to 2000 psi.	
7. Knock out CIBP @ 6850' and clean out to ±7500'.	
8. Set a CIBP @ ±7450' and cap w/1 sx cmt.	
9. Perforate Wantz Abo 7014' - 7349' (1 JSPF).	
10. Acidize Wantz Abo 7014' - 7349' w/5000 gals 15% HCl-NEA. 11. Run base GR/Temp Survey.	
12. Acid frac Wantz Abo 7014' - 7349' w/33,000 gals 20% Tital XL acid/5	w/30% CO2 + 46 hall
sealers.	
13. Install production equipment and return well to production.	
is. I hereby certiff that the information above is true and complete to the best of my knowledge and belief.	•
ustiastes A. J. FORE TILE SUPERVISOR REG. & PERMITTIN	G DATE APRIL 11, 1985
ORIGINAL SIGNED BY JERRY SEXTON	APR 1 6 1985
APPROVED BY DISTRICT SUPERVISOR	_ BATE