

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name STATE SEC. 2
8. Well No. 14
9. Pool name or Wildcat HARE SIMPSON

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Shell Western E&P Inc.	
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (LOCK 4587)	
4. Well Location Unit Letter <u>N</u> : <u>3630</u> Feet From The <u>SOUTH</u> Line and <u>1770</u> Feet From The <u>WEST</u> Line Section <u>2</u> Township <u>21S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3496' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TA'D <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-26 TO 8-28-92:

NOTIFIED NMOCD OF WELL BEING TA'D. POH W/PROD EQMT. CO W/SCRPR TO 7620'. SET CIBP @ 7597'. LD CSG W/300 BBLS FW. PT CSG TO 500# FOR 30 MIN, HELD. (CHART ATTACHED) CIRC INHIB FL. SECURED WELL FOR TA'D STATUS. CLN LOC. WELL TA'D.

PURSUANT TO THE PROVISIONS OF NMOCD RULE 203, SHELL WESTERN HEREBY REQUESTS TEMPORARY ABANDONMENT STATUS FOR A PERIOD OF FIVE YEARS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE TECH. MANAGER - ENVIR. ENG. DATE 9/09/92
TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3797

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE


DATE

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 9-10-97

SEP 14 '92

8



Robert M. Abbott

Shale Western
State Section 2
T-21-5
R-37-E
3 & P INC.
Well #14

T.H.

Casing Test

RECEIVED
SEP 11 1992
OCD HOBBS OFFICE
GOLD STAR SERVICE CO. INC.
LEASE # Sec 2
Casing PSI
TIME
REMARKS
Well TRID
DATE 8-27-92
14