

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-06398</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT <u>1045</u>	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER			
2. Name of Operator Shell Western E&P Inc.		8. Well No. 203	
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 <u>(WCK 4413)</u>		9. Pool name or Wildcat <u>577-103</u> N. EUNICE BLINEBRY/TUBB/DRNKRD	
4. Well Location Unit Letter <u>P</u> : <u>3200</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>4</u> Township <u>21S</u> Range <u>37E</u> NMPM LEA County		10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3474' DF</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>TA'D</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE H103.

11-22 TO 11-26-91:

POH W/PROD EQMT. CO TO 6865'. SET CIBP @ 6525' & CAPPED W/35' CMT. SET 2ND CIBP @ 5500' & CAPPED W/35' CMT. PT CSG TO 500# FOR 30 MIN, HELD. CIRC'D INHIB FL. SECURED WELL FOR TA'D STATUS. CLN LOC. WELL TA'D.

PURSUANT TO THE PROVISIONS OF NMOCD RULE 203, SHELL WESTERN HEREBY REQUESTS TEMPORARY ABANDONMENT STATUS FOR A PERIOD OF UP TO FIVE YEARS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>W. F. N. Kelldorf</u>	TITLE <u>DIV. ENVIRONMENTAL ENGR.</u>	DATE <u>1/02/92</u>
TYPE OR PRINT NAME <u>W. F. N. KELLDORF</u>	TELEPHONE NO. <u>713/870-3426</u>	


(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary Abandonment Expires 1-7-96

JAN 07 '92



REC

MAN

06

REC