NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

otice of Intention Change Plans		Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
OTICE OF INTENTION PLUG WELL		Notice of Intention to Plug Back.	X	Notice of Intention to Set Linea	
otice of Intention Squeeze		Notice of Intention to Acidize	X	Notice of Intention to Shoot (Nitro)	
otice of Intention Gun Perforate	Х	Notice of Intention (Other)	i	Notice of Intention (Other)	
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO		Roswell, New Mexico			
WIA FE, NEW MEXICO		(Place)		(Date)	
entlemen:				,	
Following is a Notice of Int	ention to do	certain work as described below a	t the		
Sholl 0:1	. Company	Livingston		Well Noir	?
DIETT OT			•		(Omt)
E NE 1/ of 5	ny or Operator)	21S 37E	NMPM	Wantz-Abo	
Lea	FULI (FOLLOW	nty. L DETAILS OF PROPOSEI INSTRUCTIONS IN THE RU	PLAN O	F WORK	
Pull rods, pump a set CIBP 6 6850' Run GR/CCL survey Perforate 6572' Run tubing open a Wash perforations Swab test.	FULI (FOLLOW and tubin and cap r from 68 - 6576', ended w/r s w/500 g	nty. L DETAILS OF PROPOSEI INSTRUCTIONS IN THE RU W/cement.	PLAN OLES AND PL	F WORK REGULATIONS) 6646' - 6654' w/2 3 2000 gallons 15% NEA	JSPF•
Pull rods, pump a set CIBP 6 6850' Run GR/CCL survey Perforate 6572' Run tubing open of Wash perforations Swab test.	FULI (FOLLOW and tubin and cap from 68 - 6576', ended w/r s w/500 g	L DETAILS OF PROPOSEI INSTRUCTIONS IN THE RU 'S. W/cement. 800' to 3100'. 6532' - 6533', 6606' retrievable packer. gallons 15% BDA, then contingent on testing	PLAN OLES AND PL	F WORK REGULATIONS) (646' - 6654' w/2 2 (2000 gallons 15% NEA	JSPF•

Address Box 1353, Roswell, New Mexico