

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

(Form C-102)  
(Revised 7/1/52)

**NEW MEXICO OIL CONSERVATION COMMISSION**  
**Santa Fe, New Mexico**

**MISCELLANEOUS NOTICES**

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

**Indicate Nature of Notice by Checking Below**

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE	X	NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER) TO FRAC	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Roswell, New Mexico

September 18, 1963

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Shell Oil Company Taylor-Glenn Well No. 7 in H  
(Company or Operator) Lease (Unit)  
Lot 8 1/4 of Sec. 4, T. 21S, R. 37E, NMPM., Terry-Blinbry Pool  
(40-acre Subdivision)  
Lea County.

**FULL DETAILS OF PROPOSED PLAN OF WORK**  
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

**PROPOSED OPERATION:**

1. Kill well and pull tubing.
2. Plug back w/sand to 5805'+
3. Run GR base log and perforate w/4 JS at 5798'.
4. Run tubing w/FERC and squeeze perforations at 5798' to 4300 psi.
5. Drill out to below squeeze perforations, WOC 36 hours and test squeeze to 4300 psi.
6. Treat via 5 1/2" casing w/30,000 gallons lease containing 1#/gallon Radioactive 20-40 mesh sand and 1/20#/gallon Mark II Adomite.
7. Clean out sand if necessary.
8. Run production equipment, swab test, place on production.

Approved....., 19.....  
Except as follows:

Shell Oil Company

Company or Operator

By..... R. A. Lowery Original Signed By  
R. A. LOWERY

Position..... District Exploitation Engineer  
Send Communications regarding well to:

Approved  
OIL CONSERVATION COMMISSION

By.....  
Title.....

Name..... Shell Oil Company

Address..... P. O. Box 1858, Roswell, New Mexico 88201