Box 1545 Hobbs, New Mexico July 12, 1949

Mr. E. G. Rodman Box 591 Odessa, Texas

Dear Mr. Rodman:

Just received the report of running casing on your well #1 Curry in Section 7, T. 21s, R. 37E, and wish to advise that this program does not meet with the requirements of the Oil Conservation Commission due to the fact that you have not run casing or cemented your oil string with sufficient amount of cement to protect the salt section.

You will notice your Form C-101, on approval I stated in the left hand corner that cement must return to the top of the salt section on your oil string of casing.

It will be necessary for you to two stage this at the top of the salt section. I am holding Form C-102 and Form C-103 until I hear from you.

Rest Hallia Gas Inspector

ROY:cg

enter a service 

and the state of t

n de view de la grande de la companya de la grande de la g En la companya de la grande de l En la companya de la grande de l 

Pay yarbineigh.