well 🗹

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR P.O. Ber 460

> AT TOP PROD. INTERVAL: AT TOTAL DEPTH:

REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES -ABANDON\*

(other)

## COPY TO O. UNITED S

120 m. 71.70 88240

SUBSEQUENT REPORT OF:

DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY** 

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

other

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,

AT SURFACE: 660 FSL and 1980 FEL

gas

well

Continental (ili Co

TO 0.	C C	Budget Bureau No. 42-R142
- 0,	5. LEASE	
	NM 2517	2
	6. IF INDIAN, ALI	LOTTEE OR TRIBE NAME
ELLS	S 7. UNIT AGREEMENT NAME	
a different	NMFU	·
	8. FARM OR LEAS	SE NAME
	HAWK B-	
	9. WELL NO.	
	12	
	10. FIELD OR WILI	
	GRAYBURG	LEUMONT GAS
٥	11. SEC., T., R., M	I., OR BLK. AND SURVEY O
pace 17	AREA	
	SEC B T	215 R37E
		ARISH 13. STATE
	LEA	NM
NOTICE,	14. API NO.	· · · · · · · · · · · · · · · · · · ·
1107102,	15 FLEVATIONS	
	15. ELEVATIONS (	(SHOW DF, KDB, AND WD
OF:	3503'GL	•
me.	<b>ചെ</b> ന്നിക	
기기	6617611	
uu —	change on	s of multiple completion or zon
A	PR 25 1979	s of multiple completion or zon orm 9–330.)
(1)		
	EULOCICAL SURVI	
, , ,	DO, E DU MIDXICO	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

In order to develop Penrose Skelly Pool oil reserves and prevent offset drainage, it is proposed to dual complete this zone with the existing Eumont Pool gas completion.

## RECOMPLETION PROCEDURE

- 1. Rig up. Kill well w/calcium carbonate slug pumped in foamed KCl water.
- 2. Lower 2 3/8" tbg. to 4000'. Tag for fill. C.O. to 4000' if necessary. Spot 215 gallons 15% NE-HCl acid from 3850' to 3720'. POOH.

		' * ·
Subsurface Safety Valve: Manu. and Typ	e	Set @ Ft.
18. I hereby certify that the foregoing is	true and correct	
SIGNED Would. Thutter	TITLE Admin. Sup	DATE 4-20-75
V	(This space for Federal or State offic	e use)
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		APPROVED
NMFY 4	Y	APR 25 1979
FILE		APR & S
,	*See Instructions on Reverse Sig	DISTRICT ENGINEER
		I SO DISTRICE

- 3. G.I.H. w/4" hol / carrier decentralized select re casing gun, 0° phasing, 1 JSPF. Perforate the Grayburg Formation @ 3773 , 3782', 3790', 3795', 3810', 3820', 3826', (7 holes). Perforate from top to bottom of interval. (Casing collars @ 3715'+, 3744'+, 3778', 3810'+, 3843'+). POOH.
- 4. G.I.H. w/2 7/8" tbg. and treating packer. Set packer @ ±3730'. Breakdown Grayburg perforations from 3773'-3826' w/1500\* gallons 15% NE-HCl acid @ 4 BPM utilizing 14 7/8" RCN ballsealers. Release two ballsealers every 200 gallons (4.8 bbls.). Run packer down thru perforations to free ballsealers. Set pkr. @ 3730'. \*215 gal./perf or 43 gal./ft. NEP (NEP ≈35')
- 5. Fracture treat Grayburg perfs @ 3773'-3826' @ 9 BPM thru 2 7/8" tbg. w/the following treatment

Estimated WHTP = 3200 psi. Casing burst pressure - 4300 psi. (A) 3500 gal. (83 bbl.) gelled fluid pad.

- (B) 2000 gal. (48 bbl.) frac fluid w/1/2 PPG. "20-40" mesh sand.
- (C) 2000 gal. (48 bbl.) frac fluid w/1 PPG. "20-40" mesh sand.
- (D) 3000 gal. (71 bbl.) frac fluid w/1 1/2 PPG. "20-40" mesh sand.
- (E) 5000 gal. (119 bbl.) frac fluid w/2 PPG. "20-40" mesh sand.
- (F) 6000 gal. (143 bbl.) frac fluid w/2 1/2 PPG. "20-40" mesh sand.
- (G) 6000  $\overline{gal}$ . (143 bbl.) frac fluid w/3 PPG. "20-40" mesh sand.
- (H) Flush to 50' above top perf. Do not overflush.

Total gelled fluid volume - 27,500 gal. (655 bbls.) Total frac sand weight - 50,500#

- 6. Record ISIP & @ 5 min. intervals for 15 min. SION. Swab well in.
- 7. POOH R.I.H. w/2 3/8" tbg., dual production pkr. vent string, & S.N. Set pkr. @ 3730' & S.N. @ 3830'.

- 8. Pump 2000 gal. 70 quality foamed 15% NE-HCl acid down annulus to dissolve calcium carbonate plug at Eumont perfs. Increase rate up to 3-4 BPM as pressure permits.
- 9. Install production facilities & place well on test. Report results to Division Office.

## FRAC FLUID COMPOSITION - WESTERN

entre de la company de la comp

- A) 170#/M gal. KCl clay swelling control
- B) 30#/M gal. J-13 gelling agent
- C) 25 #/M gal. Aqua seal II fluid loss additive
- D) 5#/M gal. P-4 Ph control
- E) 2 gal./M gal. FS-2 fluorocarbon surfactant
- F) 1 gal./M gal. TIC complexer
- G) 1#/M gal. B-11 breaker