

CONTINENTAL OIL COMPANY 13 13 13

P. O. Box 68
Eunice, New Mexico
March 20, 1959

New Mexico Oil Conservation Commission P. O. Box 2045 Hobbs, New Mexico

Attention: Mr. R. F. Montgomery

Gentlemen:

While taking a packer leakage test on our Hawk B-10 No. 1 in B-10-21-37, a Tubb-Drinkard dual completion, an indication of communication was discovered. By setting a tubing plug and exerting pressure on the tubing it was found that the leak is in the tubing. The Tubb zone has been quite weak and in order to evaluate the desirability of running an additional tubing string to unload liquid accumulation we have blanked off the Drinkard zone with a tubing plug and opened the Tubb to the tubing by opening a Garrett sleeve valve. The Drinkard, therefore, is temporarily shut-in and the Tubb zone alone is producing.

Yours very truly,

J. R. Parker

District Superintendent

of Production Eunice District

JRP-BLF

CC: RLA-2

PIONEERING IN PETROLEUM PROGRESS SINCE 1875