



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No.

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

....., 19.....

Well No. is located ft. from $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line and ft. from $\begin{Bmatrix} E \\ W \end{Bmatrix}$ line of sec.

.....
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
.....
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After workover: Oil: Pay Brinkard 6602-6711'. Perf 6602-14', 6722-28', 6634-40', 6650-57', 6662-77', 6684-76', 6705-11'. Flowing 5 bbls oil, 2 bbls water, in 24 hrs thru 5/8" choke on intermitter. TP 1504, CP 04, gas volume 7.9 MCFTD, GOR 1580, daily allowable 5 bbls oil. Tested 12-19-56. Gas: Pay Tubb 6190-6250'. Perf 6190-6250'. Calculated open flow potential 535 MCFTD. GOR 1880 FOG. Deliverability: at 600 PSIG 442 MCFTD, at 150 PSIG 523 MCFTD. Estimated daily allowable 500 MCFTD. Tested 12-17-56. The tubb Gas Zone of this well is designated Hawk B-10 Unit No. 1.

Workover started 10-29-56, completed 12-17-56.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company

Address

ILLEGIBLE

By

Title