

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME NORTHEAST DRINKARD UNIT	
2. NAME OF OPERATOR SHELL WESTERN E&P INC. (4431 WCK)		8. FARM OR LEASE NAME NORTHEAST DRINKARD UNIT	
3. ADDRESS OF OPERATOR P. O. BOX 576, HOUSTON, TEXAS 77001		9. WELL NO. 406	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FNL & 1650' FEL OF SECTION 10		10. FIELD AND POOL, OR WILDCAT NORTH EUNICE-BLINEBRY-TUBB-DRINKARD OIL & GAS	
14. <del>XXXXXXX</del> API # 30-025-06451		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC 10, T 21-S, R 37-E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3434' GR		12. COUNTY OR PARISH LEA	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT ☐CMT SQZ, LOG, OAP & AT ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8-22-88 thru 8-31-88:

POOH w/ prod equip. Tag PBTD @ 6722'. Ran GR/CNL/CCL from 6700' - 5000'. Cmt Sqz w/ 75 sxs class "C" cmt + .3% Halad-9 followed by 75 sxs class "C" cmt, using CICR set @ 6715'. Perf Blinebry/Tubb/Drinkard 5704' - 6690' w/ 1JSP2F. Selectively AT Blinebry/Tubb/Drinkard 5704' - 6690' w/ 14,154 gals 15% HCL acid + 145 ball sealers, using RBP's and pkr's. RIH w/ prod equip. Well returned to production 8-31-88.

RECEIVED  
MAR 29 11 00 AM '89  
CARLSBAD AREA OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

*W.F.N. KELLDORE*

TITLE

STAFF PRODUCTION ENGINEER

DATE

MAR 24 1989

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

SJS

CARLSBAD, NEW MEXICO