

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-11349

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name <u>Nolan-Wente State 10</u>
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>State 10</u>
3. Address of Operator <u>P. O. Box 460, Hobbs, New Mexico 88240</u>	9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>10</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat <u>Drinkard/Bleeker</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUS AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUS AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER <u>DHC; acidize</u>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

MIRU. Mill pkr & pull pkr out of hole. CO to 6557'. Set RBP @ 6730' & pkr @ 6704'.
Spot 2 bbls xylene over perfs 6704'-6624'. Acidize w/ ^{94 bbls} 15% HCL-NE-FE. Pmpd 350
psi graded rock salt in 5 1/2 bbls gelled brine & 15% HCL-NE-FE. Flush w/35 BTFW.
Rel pkr. Reset RBP @ 6618'. Spot 1 1/2 bbl xylene over 6555'-6506'. Pull pkr to 6450'.
Acidize w/40 bbls 15% HCL-NE-FE. Flush w/28 BTFW. Rel RBP & reset @ 6000'.
Spot 4 bbls xylene over 5882'-5723'. Set pkr @ 5700'. Acidize w/ ^{30 bbls} 15% HCL-NE-FE.
Flush w/26.5 bbls 2% KCL TFW. Rel RBP & pkr. Ran prod. equipmt. Pmpd 21 BO,
5 BW & 73 MCF on 1/21/85

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry Sexton</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>3/5/85</u>
ORIGINAL SIGNED BY JERRY SEXTON		
DISTRICT I SUPERVISOR		
APPROVED BY	TITLE	DATE

MAR - 7 1985

RECEIVED

MAR -6 1985

**O.S.D.
HOUSE OFFICE**