NEW EXICO OIL CONSERVATION COMPISSION

SANTA FE, NEW MEXICO

## MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable or the rejection by the Commission or agent, of the plan submitted. The plan submitted should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ommission.						
			Indicate	nature of notice by c	hecking below:		
	CE OF INTI	ENTION TO T	EST CASING	<b>T</b>	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL		
		ENTION TO C	HANGE PLAN	S NOT	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING		
NOTI	CE OF INT	ENTION TO F	REPAIR WELL	NOT	ICE OF INTENTIO	N TO PLUG WELL	
NOTI	CE OF INT	ENTION TO I	DEEPEN WEL	L			
				Midland,	l'exas	December 12, 1	951
Santa Gentl	a Fe, New Molemen:			a work as described	below at the	6	
Нази	hle Oil	& Refining	Co.	. M. State "Y"		Well No8in	NE/4 of SE
1144	Company or O	perator	3 G D	Lease	<sub>Р М</sub> Brunso	<u>a</u>	Field.
of Se	.c10		<b>1–5</b> R				
			(		D DIAN OF WO	ND IZ	
				LS OF PROPOSE			•
	F	OLLOW INSTI	RUCTIONS IN	THE RULES AND I	REGULATIONS OF	THE COMMISSION	
			Set 11-3/4	-inch casing as	follows:		
					Total Depth	Cmt. &	Plug on Bottom
i ze	Amount	Weight	Set At	Formation	of Well	Make Cut.	DOCCOM
31 ze 11-3/4	Amount 289'	Weight 55#	305'	Formation Lime & sand	of Well 307'	Make Cut.  350 sx. Trinity Neat	12:30 P.
11-3/4	289'	55# nod used.	305°		307'	350 sx.	12:30 P.
l=3/4 (allibu: Circ. of vill te	289'	55# nod used. cks excess g with 800#	305°	Lime & sand	307' 2-51.  Humble gifts	350 sx. Trinity Neat Cmt.  Company or Operator Company or Operator Division Superir	12:30 P. 12-11-51.
l=3/4 (allibu: Circ. of vill te	289° rton method 15 sac st casing	55# nod used. cks excess g with 800#	cmt. # press. at	Lime & sand	307' 2-51.  Humble Cit & Asst.  Fosition Asst.  Send com	350 sx. Trinity Neat Cmt.  Company or Operator Company or Operator Division Superir munications regarding	12:30 P. 12-11-51.
l=3/4 (allibu: Circ. of vill te	rton methut 15 sac est casing	55# nod used. cks excess g with 800#	cmt. # press. at	Lime & sand	307' 2-51.  Humble Cit & By  Fosition Asst. Send com	350 sx. Trinity Neat Cmt.  Company or Operator Company or Operator Division Superir munications regarding	12:30 P. 12-11-51.  12:30 P. 12-11-51.
1-3/4 (allibu: Circ. of	rton methut 15 sac est casing	55# nod used. cks excess g with 800#	305' emt. # press. at	Lime & sand	307' 2-51.  Humble Cit & By  Fosition Asst. Send com	350 sx. Trinity Neat Cmt.  Company or Operator Company or Operator Division Superir munications regarding	12:30 P. 12-11-51.  12:30 P. 12-11-51.
1-3/4 (allibudire. of fill te	rton methut 15 sac st casing	55# nod used. cks excess g with 800#	emt.  press. at  EC 14 195	Lime & sand	307' 2-51.  Humble Cit & By  Fosition Asst. Send com	350 sx. Trinity Neat Cmt.  Company or Operator Company or Operator Division Superir munications regarding	12:30 P. 12-11-51.  12:30 P. 12-11-51.