SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of in the Commission.

Indicate nature of notice by checking below.

			Indicate nat	ture of notice	by checkin	ng below:	•	
	CE OF INT HUT-OFF	ENTION TO TES	T CASING	X	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL			
NOTI	CE OF INT	ENTION TO CHA	NGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING			
NOTI	CE OF INT	ENTION TO REP	AIR WELL		NOTICE (F INTENTIO	N TO PLUG WELL	
NOTI	CE OF INT	TENTION TO DEE	PEN WELL					
		Hoh	ba, New Me	xico	Pla	.ce	March 17 _{Bat} 1952	
	CONSERVA Fe, New M	TION COMMISSIO						
Gentle	emen:							
	Company or O	& Refining C	ompany	N. M. St	ate #V#	V	Well No9 in NE/4	of SW/
			, R 37	F N.	M. P. M.,	········Press eco		Field.
						DI GHAQI	1	
		FULI	L DETAILS	OF PROPO	OSED PL	AN OF WO	RK	
	Fr(THE COMMISSION	
	• •							
		51	et 5 1/2"	casing as	rollows	:\$		
9	Amount	Weight	Set at	Format:		Total Dept	h No. Sacks &	Pl Bo
/2"	82261	736.08 of 14# 1019.69 of 15.50# 6470.43 of 17#	82401	Granite 1	la s h	82401	450 sx. 10% Gel Trinity Port- land Cement	12:1 3-1
of c	ement 35	Inc., method 50' from surf with 1000# a	ace.	M. 3-16-5	2			
Approvedexcept at follows:				, 19	Humb	le 011 & R	Cining. Company	
					Ву	901 2	Mille.	
					Position	District Send comm	t Superintendent unications regarding well to	
	OIL C	CONSERVATION	COMMISSION,				-L1-t-t1-	
By P. S. Man							4	
	······				Address	Box 23	347	
Title			/			Box 23	New Mexico	

nja i ji ji gota ka prisida ka dibi ka ma Kanda

Programme and the state of the

... $\mathcal{V}(x,y) = \{x \in \mathcal{X} \mid x \in \mathcal{X}\}$

 $\phi_{ij}(x,y) = 0$ (1)