

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER INJECTOR

2. Name of Operator

Shell Western E&P Inc.

3. Address of Operator

P.O. Box 576 Houston, TX 77001-0576

(WCK 44-13)

8. Well No.

503

9. Pool name or Wildcat

N. EUNICE BLINEBRY-TUBB-DRNKRD

4. Well Location

Unit Letter K : 2080 Feet From The SOUTH Line and 2080 Feet From The WEST Line

Section 10 Township 21S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3470' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: INJ PROFILE CORR

☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH W/INJ EQMT.

2. CO TO PBTD @ +/-7100'.

3. SET CIBP @ 6020'.

4. RIH W/DMP BLR. FILL HOLE W/SD TO BTW 5770' & 5780'.

5. SET CIBP @ 5772' & CIBP @ 5550'.

6. SQZ BLINEBRY PERFS 5594' - 5760'. (CMT DESIGN TO BE DETERMINED AT A LATER DATE.)

7. WOC AT LEAST 24 HRS.

8. DO CIBP & CMT TO CIBP @ 5772'. PT SQZ @ 5700' & 5770' TO 500#. CONT DRLG OUT THRU CIBP @ 5770'. CO SD TO TOP OF CIBP @ 6020'. DO CIBP.

9. TIH W/RBP & PKR. PT PRIOR TUBB SQZ (7/88) TO 500#.

10. ACDZ BLINEBRY-TUBB-DRINKARD PERFS 5776' - 6729' W/9450 GAL 15% NEFE HCL + 1050# ROCK SALT. POH W/TBG & TOOLS.

11. INST INJ EQMT, SETTING GUIB ER-VI PKR @ +/-5530'.

12. PT TBG/CSG ANN TO 500# FOR 30 MIN. RTI.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE DIV. ENVIRONMENTAL ENGR.

DATE 1/28/92

TYPE OR PRINT NAME

W. F. N. KELLDORF

TELEPHONE NO. 713/870-3426

(This space for State Use)

FEB 03 '92

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: