

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06486
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Northeast Drinkard Unit	
8. Well No.	219
9. Pool name or Wildcat	N. Eunice Blinebry-Tubb-Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Shell Western E&P, Inc.	
3. Address of Operator P.O. Box 576, Houston, TX 77001 S.A. Galik - 5239 WCK	
4. Well Location Unit Letter N ⁽¹⁴⁾ : 3550 Feet From The South Line and 2300 Feet From The West Line Section 2 Township 21S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3499 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: OAP, AT ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-15 To 3-18-95

POOH w/prod equip. Set Pkr @ 5890'. Had comm w/prev sqzd Blinebry perfs 5848-5878. Reset Pkr @ 5827'. PT csg 500# - held. Perf the following Blinebry intervals, 5784-5876 (1 JSPF). AT 5784-5939 w/3400 gal 20% HCL. Set RBP @ 5832' and PKR @ 5765'. AT 5784-5806 w/2350 gal of 20% HCL. POOH w/RBP and PKR. Install production equipment and RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley Galik TITLE Reg. & Permit Mgr. DATE 5-3-95
TYPE OR PRINT NAME Dr: G. S. Nady TELEPHONE NO. 713/544-4219

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 11 1995

mp