Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C	-103
Revised	1-1-89

OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.	
DISTRICT II Santa Fe, New Mexico P.O. Drawer DD, Artesia, NM 88210	87504-2088	5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lease No. B-9745	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL GAS WELL X WELL OTHER		NORTHEAST DRINKARD UNIT	
2. Name of Operator SHELL WESTERN E&P INC.		8. Weil No. 316	
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK	4435)	9. NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS	
4. Well Location Unit Letter S: 2310 Feet From The SOUTH	Line and 23	07 Feet From The WEST Line	
Section 2 Township 21S 10. Elevation (Show whether	er DF, RKB, RT, GR, etc.)	NMPM LEA County	
11. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:		eport, or Other Data SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CASING TEST AND CE		
OTHER:	OTHER:	OAP & Acd	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, work) SEE RULE 1103.	and give pertinent dates, inclu	ding estimated date of starting any proposed	
7-10 to 7-17-89:			
Tagged CIBP @ 5540'. DO CIBP & CO + (1 JSPF). Acd perfs 5774' - 5942' W/3150 prod equip & retd to prod	0 5950' (TD). gals 15% HCI +	Perf'd Blinebry 5849' - 5942' 1000# rock salt. Installed	
I hereby certify that the information above is true and complete to the best of my knowledge	and belief.	UDV - 0-22- 3 0	
SIGNATURE	TITLE REGULATORY S		
TYPE OR PRINT NAME J. H. SMITHERMAN	(7	13) 870-3797 TELEPHONE NO. AUG 2 5 1989	
(This space for Stat DELIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		AUG & n 1300	
APPROVED BY	TITLE	DATE	
CONDITIONS OF APPROVAL, IF ANY:	. • •	i	

RECEIVED

AUG 24 1989

OCD HOBBS OFFICE

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL API NO.	,	
5. Indicate Type of L	STATE X	· FEE
6 State Oil & Gos I	esse No	

1000 Rio Brazos Rd., Aziec, Rivi 87410	·B-9745			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name			
1. Type of Well: OIL GAS WELL X WELL OTHER	NORTHEAST DRINKARD UNIT			
2. Name of Operator	8. Well No. 316			
SHELL WESTERN E&P INC. 3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS			
4. Well Location Unit Letter S: 2310 Feet From The SOUTH Line and 2307 Feet From The WEST Line				
Section 2 Township 21S Range 37E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3491 ' KB				
Check Appropriate Box to Indicate Nature of Notice, Renamed Notice of Notice of Notice, Renamed Notice of Notice of Notice, Renamed Notice of	eport, or Other Data SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING			
TEMPORARILY ABANDON . CHANGE PLANS . COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING CASING TEST AND CE	EMENT JOB .			
OTHER: OAP & Acdz OTHER:				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				

DV JEDRY SEXTON		JIIN 2 G 1989
TYPE OR PRINT NAME J. H. SMITHERMAN		
	(713) 870-3797	TELEPHONE NO.
SKINATURE	•	
I hereby certify that the information above is true and complete to the best of my knowledge a SKINATURE SKINATURE	REGULATORY SUPV.	_ DATE 6-22-01
I hereby certify that the information above is true and complete to the best of my knowledge a	and obtained.	(22 09
1	and belief.	
·		

(This space for State UNIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

1. DO CIBP @ 5550'. Cont CO to 5950' (TD).

2. Perf Blinebry 5849'-5942' (I JSPF).
3. Acdz perfs 5774'-5942' W/3150 gals 1590 NEFE HCI + 1500# rock salt.
4. Install prod equip & ret well to prod.