Form 3160-5 (June 1990)

UN. ED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135

		Expires:			
5.	Lease	Designat	ion and	Serial	No.

NM-2512

SUNDRY NOTICES AND REPORTS ON WELLS

6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE I. Type of Well Oil Well Gas Well U Other 8. Well Name and No. Hawk B-3 No. 9 2. Name of Operator 9. API Well No. Conoco Inc. 30-025-06501 3. Address and Telephone No. (915) 686-5583 10 Desta Drive W. Midland, TX 79705 10. Field and Pool, or Exploratory Area 4 Location of Well (Footage, Sec., T., R., M., or Survey Description) Tubb Gas 11. County or Parish, State Unit R 3-215-37E Lea, NM 1650' FSL & 1650' FEL 12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Nonce Altering Casing Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* MIRU. Fump 70 bbls mud to kill well & load hole from 6345' - 7515' 5-18-90 MIRU. Pump 70 bbls mud to kill well & load hole from 6345' - 7515'. Tried to jar pkr loose - could not. GIH to 6188' w/jet cutter & cut prod tbg off. GIH w/csg scraper to 6135'. POOH. Set cmt rtnr @ 6100'. Test tbg to 1000 psi. Circ hole w/150 bbls mud. Circ out a 17' piece of 2" hose. Tst csg to 500 psi. Sting back into ret & test annulus to 500 psi. Pump 60 sx Class H cmt below ret to squeeze Tubb perfs. Sting out of ret & spot 12 sx Class H cmt on top of ret. Displ w/35 bbls mud. PUH to 5784'. Load hole w/1 bbl mud. Pump 23 sx Class H cmt & displ w/32 bbls mud. PUH to 3204'. Load hole w/5 bbls mud. Pump 11 sx Class C cmt & displ w/18 bbls mud. PUH to 1493'. Load hole w/4 bbls mud. Pump 11 sx Class C cmt & displ w/8 bbls mud. POOH w/remaining tbg. Perf 5 1/2" csg @ 316'. Pump 10 bbls mud to load hole & circ. Pump 65 sx Class C cmt to fill 7 5/8" annulus & set surf plug in 5 1/2" csg. Cut off WH & install P&A marker. P&A marker. $\overline{\sigma}$ 8 w 14. I hereby certify that the foregoing is true and correct 09-24-1990 Sr. Analyst - Production Title (This space for Federal or State office use) Approved by Title Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED

OCT 2 3 1990

OCD HOBBS OFFICE