

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI-CATE
(Other instruct
verse side) 00 re

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-2512

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

NORTHEAST DRINKARD UNIT

8. FARM OR LEASE NAME

NORTHEAST DRINKARD UNIT

9. WELL NO.

109

10. FIELD AND POOL OR WILDCAT
NORTH EUNICE BLINEBRY-
TUBB-DRINKARD OIL & GAS

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 3, T21S, R37E

12. COUNTY OR PARISH

LEA

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☐ OTHER INJECTOR

2. NAME OF OPERATOR

SHELL WESTERN E&P INC.

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface

660' FNL & 1980' FEL SEC. 3

14. XXXXXX API NO.

30-025-06510

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3502' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6-23 to 6-29-88:

POH w/inj equip. Set pkr @ 5510'. Sqzd Blinebry perfs 5762' - 5990' w/100 SX Cls "C" cmt + .3% Halad-9 followed by 75 SX Cls "C" cmt + 2% CaCl₂. POH w/pkr. DO cmt 5619' to 5960', fell thru. Tagged PSTD @ 6002'. Perf'd Blinebry 5852' - 5985' (1JSPF & 1JSPZF). Acid perfs 5852' - 5985' w/4200 gals 15% HCl-NEA + 750# rock salt. Installed inj equip, setting Guib ER-VI Pkr @ 5708'. Pres tstd csg to 350# for 30 min, held OK.

9-09-88:

Commenced inj.

18. I hereby certify that the foregoing is true and correct

SIGNED Marcus Linker for A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE 1-18-89

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

SJS