

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Offic	L	16	Crue	•
Lease No.	LC	03	2096	b
Unit	H	U		

NOTICE OF INTENTION TO DRILL	SU	BSEQUENT REPORT OF WATER S	THE OFF	XX
NOTICE OF INTENTION TO CHANGE PLANS	1			
NOTICE OF INTENTION TO TEST WATER SHUT-		SSEQUENT REPORT OF SHOOTING	G OR ACIDIZING	
NOTICE OF INTENTION TO RE-DRILL OR REPAI		SSEQUENT REPORT OF ALTERING SSEQUENT REPORT OF RE-DRILL	G CASING	· i
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SEQUENT REPORT OF ABANDON		
NOTICE OF INTENTION TO PULL OR ALTER CAS	SINGSUI	PLEMENTARY WELL HISTORY	MENI	
NOTICE OF INTENTION TO ABANDON WELL				
(INDICATE ABOVE	BY CHECK MARK NATURE	OF REPORT, NOTICE, OR OTHER D.	ATA)	
Lockhart 9-11		j	une 27	10 5
7.11 Nr \$4	** (N)			
ell No. 14-TB is located 16			line of s	ec. 11
	37 (Range)	(Meridian)	· 	
Terry Eliaebry			o tāmandan	
(Field)	(County or Subdivisi		tate or Territory)	
ate names of and expected depths to objective ing p	DETAILS OF sands; show sizes, weights soints, and all other impor	tend lauration of	s; indicate mudding	jobs, cement
	sands; show sizes, weights soints, and all other impor	and lengths of proposed casing tant proposed work)		
Hen 183 joints of 5 g down 6-20-57. Top o	sands; show sizes, weights soints, and all other impor	and lengths of proposed casing tant proposed work)		
Hen 183 Joints of 5 g down 6-20-57. Top og 1000-1000g. To 5925	sands; show sizes, weights so ints, and all other importants, and all	and lengths of proposed casing tant proposed work) Set # 574	th AUO 34:	cka, drillin
ion 183 joints of 5 g down 6-20-57. Top og 1000-1000g. To 5925 understand that this plan of work must receimpany. Continental C11	sands; show sizes, weights so ints, and all other importants, and all	and lengths of proposed casing tant proposed work) Set # 574	th AUO 34:	cka, drillin
Hen 183 Joints of 5 g down 6-20-57. Top og 1000-1000g. To 5925	sands; show sizes, weights so ints, and all other importants, and all	and lengths of proposed casing tant proposed work) Set # 574	th AUO 34:	cka, drillin
ion 18) joints of 5 g down 6-20-57. Top og 1000-1000#. To 5925 understand that this plan of work must receimpany Continental C11	sands; show sizes, weights soints, and all other importants are all other importants are all other importants and all other importants are all other importants and all other importants are all other importants are all other importants are all other importants and all other importants are all oth	and lengths of proposed casing tant proposed work) Set # 574	t before	cka drillin