

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER temp. abandoned
2. NAME OF OPERATOR CONOCO INC.
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface Unit D
330' FNL & 330' FWL
14. PERMIT NO. 30-025-06542
15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO. LC-032096(B)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Lockhart B-12
9. WELL NO. 7
10. FIELD AND POOL, OR WILDCAT Blinbry Oil & Gas
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12-215-37E
12. COUNTY OR PARISH Lea
13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☐	FRACTURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other) <u>test csq for BLM and return to Prod.</u>	☒
(Other)	☐	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU ON 2-27-86
- ② Set RBP @ 5890' & pkr @ 5720'. Test RBP to 1500 psi. Test csq to 500 psi, test was witnessed by BLM representative.
- ③ Reset RBP @ 5890' & pkr @ 5720' and acidized w/ 20 bbls 15% HCL, flushed w/ 25 bbls TFW. Swab.
- ④ Re pkr & RBP & POOH. Ran prod. equip. Rig down on 3-4-86.
- ⑤ Swab tested. 7 BO & 2 BW on 3-7-86.

ACCEPTED FOR RECORD

SWR
MAR 17 1986

CARLSBAD, NEW MEXICO

18. Bureau certifies that the foregoing is true and correct

SIGNED [Signature] TITLE Administrative Supervisor DATE 3-11-86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side