Form	9-331
t May	1963)

TEST WATER SHUT-OFF

FRACTURE TREAT

PRACTURE TREATMENT

SHOOTING OR ACIDIZING

form approved. Budget Bureau No.	42-R142
5. LEASE DESIGNATION AND S	ERIAL NO

ALTERING CASING

ABANDON MENT*

orm 9-331 May 1963)	UNITED TATES DEPARTMEN OF THE INTE GEOLOGICAL SURVEY		Bridget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. 1. LEASE DESIGNATI
Sl (Do not use	UNDRY NOTICES AND REPORTS this form for proposals to drill or to deepen or phonon for PERMIT—" for such	S ON WELLS ug back to a different reservoir. ch proposals.)	7. UNIT AGREEMENT NAME
2. NAME OF OPERAT Continent 3. ADDRESS OF OPE P. O. BOX	al Oil Company RATOR 460, Hobbs, NM 88240 LL (Report location clearly and in accordance with	of See 13	8. KARM OR LEABE NAME LOCKHOUT B-13A 9. WELL NO. 10. EIFLD AND POOL, OR WILDCAT INTERPORT BLEND 11. SEC., T., R. M., OR BLE. AND SURVEY OR AREA SEC/3 7-2/5 R-37E 12. COUNTY OR PARISH 12. STATE Lea NM
16.	Check Appropriate Box To Indico	nte Nature of Notice, Report, o	SEQUENT REPORT OF:

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

In response to your letter dates, including estimated date of starting any estimated one concell over intent to perform Work.

Please concel our intent to perform Work.

The work well.

8. I hereby certify that the foregoing is true and correct	TITLE Admin. Supervisor	DATE 8-2-73
SIGNED M. 6 GOARLES	TITLE Admit. Supervisor	1
(This space for Federal or State office use)	TITLE TOR RELUIT	DATE
APPROVED BY	ACCEPILLY 1973	le X
*S	ee Instructions on Reverse Side U. S. GEOLOGICAL W. HOEBS, NEW MEXICA	CO
USGS 5 FILE	ee Instructions on Reverse Side U. S. GEOLOGICAL MEXI HOEBS, NEW MEXI	
