

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name STATE SECTION 15
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 3
4. Location of Well UNIT LETTER G 2210 FEET FROM THE NORTH LINE AND 2310 FEET FROM THE EAST LINE, SECTION 15 TOWNSHIP 21-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat DRINKARD
15. Elevation (Show whether DF, RT, GR, etc.) 3439' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER OPEN ADDITIONAL PAY AND ACIDIZE ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Perforate Blinebry zone 5649', 69', 71', 86', 97', 5702', 96', 99', 5837', 52' (10 holes).
2. Set RBP @5855'. Pressure test. Set FBRC @5720'. Pressure backside to 500 psi.
3. Acidize Blinebry perfs (5745' - 5852') w/3500 gals 15% NE acid.
4. Set RBP @5720'. Set FBRC @5500'.
5. Acidize Blinebry perfs (5557' - 5702') w/3500 gals 15% NE acid.
6. Retrieve FBRC and RBP.
7. Install production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MARCH 30, 1982

ORIGINAL SIGNED BY
JERRY SEXTON

APPROVED BY JERRY SEXTON TITLE DISTRICT 1 SUPR. DATE APR 2 1982

CONDITIONS OF APPROVAL, IF ANY: