

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-7-

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name STATE SECTION 15
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Well No. 4
4. Location of Well UNIT LETTER H 2310 FEET FROM THE NORTH LINE AND 990 FEET FROM THE EAST LINE, SECTION 15 TOWNSHIP 21S RANGE 37E WMPM.	10. Field and Pool, or Wildcat WANTZ ABO
15. Elevation (Show whether DF, RT, GR, etc.) 3431' DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER SQZD DRINKARD & RECOMPLETED TO WANTZ ABO <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

1-27-88: Set cmt ret @ 6325'. Sqzd Drinkard perms 6397' - 6663' w/100 sx CIs "C" cmt + .3% Halad-9 followed by 60 sx CIs "C" cmt + 2% CaCl₂.

1-28 to 1-30-88: DO cmt ret @ 6325' & cmt to 6560'. Pres tstd sqz to 500#, held OK. Tagged fill @ 7220'. CO to 7340'.

2-01-88: Ran GR/CNL/CCL from 7344' (PBTD) to 6500'.

2-02-88: Perf'd Wantz Abo 7171' - 7239' (1 JSPF).

2-03-88: Ran GR/temp survey from 6800' to 7340'. Acd perms 7171' - 7239' w/5000 gals 20% HCl-NEA + 250# rock salt.

2-05-88: Ran GR/temp survey over trtd interval.

2-08 to 2-10-88: Installed prod equip & returned well to prod.

NOTE: Prep to frac Wantz Abo.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 3-10-88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY ZA A. Drinkard TITLE 2A A. Drinkard DATE MAR 16 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 14 1988

OCD
HOBBS OFFICE