

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

## Santa Fe, New Mexico

### MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK	X	NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE	X	NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE	X	NOTICE OF INTENTION (OTHER) SAND FRAC	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Roswell, New Mexico  
(Place)

January 21, 1963  
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the

Shell Oil Company State (Sec. 15) Well No. 4 in H  
(Company or Operator) Lease (Unit)  
SE 1/4 NE 1/4 of Sec. 15, T.21S, R. 37E, NMPM, Brunson Pool  
(40-acre Subdivision)  
Lea County.

### FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

**PROPOSED OPERATION:** Abandon Brunson, recompleat in Drinkard.

1. Kill well, pull tubing and packer.
2. Set CIBP at 7350' and cap w/1 sx. cement.
3. Perforate Drinkard at 6525', 6527', 6530', 6534', 6536', 6538', 6540', 6542', 6544', 6546', 6548' w/1-3/8" JS (total 11 holes).
4. Treat w/3000 gallons 15% NEA.
5. Swab test.
6. If necessary, treat w/15,000 gallons lease crude containing 1# sand and 1/20# MARK II Adomite per gallon.
7. Bleed off pressure, check for sand fill and clean out if necessary.
8. Run 2" tubing and place on production.

Approved....., 19.....  
Except as follows:

Approved  
OIL CONSERVATION COMMISSION

By.....  
Title.....

Shell Oil Company  
Company of Operator  
By..... R. A. Lowery  
Position..... District Exploitation Engineer  
Send Communications regarding well to:

Name..... Shell Oil Company  
Address..... P. O. Box 1858, Roswell, New Mexico