

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-025-06595 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTOR | 7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT |
| 2. Name of Operator Shell Western E&P Inc. | 8. Well No. 709 |
| 3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (WCK 4435) | 9. Pool name or Wildcat N. EUNICE BLINEBRY-TUBB-DRNKRD |
| 4. Well Location Unit Letter I : 1980 Feet From The SOUTH Line and 660 Feet From The EAST Line Section 15 Township 21S Range 37E NMPM LEA County | 10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3413' GR |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: PERF'D, ACD & CTI (ORDER #R-8541) * ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-14 TO 8-21-90:
POH W/PROD EQUIP. CO TO PBTD @ 6622'. PERF'D BLINEBRY/TUBB 5672' - 6077' (2 JSPF).
SET RBP @ 6100' & PKR @ 5980'. ACD TUBB PERFS 5998' - 6077' W/1386 GALS 15%
NEFE HCL. RESET RBP @ 5745' & PKR @ 5650'. ACD BLINEBRY PERFS 5672' - 5732' W/
504 GALS 15% NEFE HCL. REL RBP/PKR, POH. INST INJ EQUIP, SETTING GUIB UNI-VI
PKR @ 5602'. PT CSG TO 500# FOR 30 MIN, HELD OK. SI WELL.

*LEASE-LINE COOPERATIVE AGREEMENT DATED 4/24/90.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W.F.N. Kelldorf TITLE DIV. ENVIRONMENTAL ENGR. DATE 12/19/90
(713)
TYPE OR PRINT NAME W.F.N. KELLDORF TELEPHONE NO. 870-3797

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

✓
12

5