			4	
NO. OF COPIES RECEIVED			*	Form C-103 Supersedes Old
DISTRIBUTION				C-102 and C-103
SANTA FE		NEW MEXICO OIL CONSE	RVATION COMMISSION	Effective 1-1-65
FILE				5a, Indicate Type of Lease
U.S.G.S.				State Fee X
LAND OFFICE				5. State Oil & Gas Lease No.
OPERATOR				
		·		Manman Manak
DO NOT USE THIS FOR	SUNDRY NOT	TICES AND REPORTS ON TO DRILL OR TO DEEPEN OR PLUG BA	WELLS ACK TO A DIFFERENT RESERVOIR.	
<u>.</u>				7, Unit Agreement Name
OIL GAS WELL X WELL	Стн	ER• •	· · · · · · · · · · · · · · · · · · ·	
2. Maine of Operator				8. Farm or Lease Name
	Marathon	0il Company		L. G. Warlick "C"
3. Address of Operator				9. Well No.
	Box 220. H	lobbs, New Mexico	88240	10
4. Location of Well	<u> </u>			10. Field and Pool, or Wildcat
T	1725	South	2149 FEET FROM	Blinebry Oil
UNIT LETTER	,	FEET FROM THE	LINE AND FEEL FROM	***************************************
<b>D</b> and	1	5 215	RANGE 37E NMPN	AIIIIIIIIIIIIIIIIIIIIIII
THE East	INE, SECTION	TOWNSHIP	RANGE NO.	
inninnin in the second second	mmm	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
		DF 343		Lea AllIIIII
16.	Check Appen	Driate Box To Indicate N	ature of Notice, Report or O	ther Data
	CHECK APPIO		SUBSEQUEN	IT REPORT OF:
NOTI	CE OF INTEN			
		PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	1		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	4	CHANGE PLANS	AND TEST AND CEMENT ION	
PULL OR ALTER CASING			OTHER Recompletion f	rom Hare-Simpson 🛛 🛛 🗙
OTHER				
		(Clearly state all pertinent det	ails, and give pertinent dates, including	ng estimated date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of star work) SEE RULE 1103.

TD 7670'. Set Baker bridge plug at 6000'. Dumped two sacks cement on plug. PBTD 5981'. Welex went in hole with select-fire jet perf. gun and perf.  $5\frac{1}{2}$ " casing with 3/8" jet shots (2 shots per ft.) at 5747, 5748 $\frac{1}{2}$ , 5750, 5753, 5763, 5771, 5775, 5791, and 5795'.

Western Company tested cast iron bridge plug to 3500#. Spotted 125 gals. 15% Spearhead acid over perfs. Set packer at 5700'. Broke down perfs. at 2700 psi. Ran 1875 gals. 15% Spearhead acid with 24 ball sealers in eight stages (3 balls per stage). Good ball action and balled out.

Sand frac with 20,000 gals. gel brine and 20,000# of 20-40 mesh sand. Over flushed with 5 bbls. brine. Max. press. 4000#, min. press. 3000. Average press. 3800#. Average injection rate 24.9 BPM. ISDP 2100#. 10 min. SDP 1900#.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Killing the internation above to the one		12-11-67
	OBICINATION CONTRACTOR	
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		