

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator SHELL OIL COMPANY 3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001 4. Location of Well UNIT LETTER M, 330 FEET FROM THE SOUTH LINE AND 990 FEET FROM THE WEST LINE, SECTION 15 TOWNSHIP 21-S RANGE 37-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3445' DF	7. Unit Agreement Name 8. Farm or Lease Name ARGO 9. Well No. 9 10. Field and Pool, or Wildcat HARE-SIMPSON 12. County LEA
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER ABANDON ELLENBURGER ZONE; RECOMPLETE IN THE HARE-SIMPSON FORMATION <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-26-82: Cleaned out to 8000'.
2-27-82: Set CIBP @ 7990' and capped w/35' of cmt.
2-28-82: Spotted 400 gals 15% NE acid from 7925' to 7525'. Perf'd 5 1/2" liner 7558' - 7925' (28 holes).
3-02-82: Set FBRC @ 7455' and acidized perfs 7558' - 7925' w/3,000 gals 15% NE acid.
3-03-82: Frac treated perf 7558' - 7925' w/38,000 gals cross-linked gelled 2% KCl + 84,000# 20-40 mesh sand + 85 tons CO₂ + 500# benzoic acid and 100# of rock salt + 1,000 gals 15% NE acid.
3-04-82: Retrieve FBRC.
3-05-82: Installed production equipment. Well complete.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Fore A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE APRIL 22, 1982

APPROVED BY JERRY SEXTON TITLE DISTRICT 1 SUPR. DATE APR 27 1982
CONDITIONS OF APPROVAL, IF ANY:

77