

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

SEP 29 1 01 PM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>5. State Oil & Gas Lease No. -</p>
<p>2. Name of Operator Shell Oil Company, Western Division</p>		<p>7. Unit Agreement Name -</p>
<p>3. Address of Operator P. O. Box 1509, Midland, Texas</p>		<p>8. Farm or Lease Name Argo</p>
<p>4. Location of Well UNIT LETTER L, 1880 FEET FROM THE south LINE AND 760 FEET FROM THE west LINE, SECTION 15 TOWNSHIP 21-S RANGE 37-E NMPM.</p>		<p>9. Well No. 10</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3453 DF</p>		<p>10. Field and Pool, or Wildcat Hare</p>
		<p>12. County Lea</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Check for sandfill and clean out, if necessary. Set blank plug in SN and pressure test tubing for packer leak.
2. If warranted, treat w/200 bbl lease crude plus 1 gal/10 bbls. Hyflo.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed By
N. W. Harrison N.W. Harrison TITLE Senior Exploitation Engineer DATE September 27, 1965

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: