NUMBER OF COPIES RECEIVED			
DIS	TRIBUTIC	N	
SANTA FE			
FILE			
U.S.G.S.			
LAND OFFICE			
TRANSPORTER	OIL		
	GAS		ſ
PHORATION OFFIC	CE		
OPERATOR			

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention	Notice of Intention to	Notice of Intention		
to Change Plans	Temporarily Abandon Well	to Drill Deeper		
Notice of Intention	Notice of Intention			
to Plug Well	to Plug Back To Set Liner			
Notice of Intention	Notice of Intention	Notice of Intention		
to Squeeze	to Acidize	to Shoot (Nitro)		
Notice of Intention	Notice of Intention	NOTICE OF INTENTION		
to Gun Perforate	(Other)	(Other)		

OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

Roswell, New Mexico May 17, 1963 (Place) (Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.

Shell	011 Company		Argo	Well N	11	in	K
(Company	or Operator)		Lease				(Unit)
NE 1/4 SW 1/4 of Se	с. <u>15</u> т.	21 S	_в 37е		XXX	Hare	
(40-acre Bubdivision)	·····, -	•••••••••••••••••••••••	····, A	.,	•••••••••••••••••••••		

Lea....County.

FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

PROPOSED OPERATION: Abandon Hare, recomplete in Blinebry Oil.

- 1. Pull 2" tubing and packer.
- Set CIBP at 7400' and cap w/cement. 2.
- 3. Run GR/N-CLL from PBTD to 2500'.
- 4. Perforate selected intervals w/3/8" JS from 5740' 5850'.
- 5. Run 3" X-line frac tubing w/FBRC. Acidize new perforations w/1500 gallons 15% NEA.
- 6. Fracture treat w/20,000 gallons lease oil.
- Pull 3" tubing an FBRC. Check for sand fill, clean out if necessary. 7.
- 8. Run 2" tubing.
- 9.. Swab test and place on production.

Approved, 19, Except as follows:	Shell Oil Company Company or OperGriginal Signed By By				
	ByR. A. LOWERY R. A. LOWERY				
Approved OIL CONSERVATION COMMISSION	Position District Exploitation Engineer Send Communications regarding well to:				
By	Name				
Title	Address. P. O. Box 1858, Roswell, New Mexico				