



## TIDEWATER OIL COMPANY

Box 547  
Hobbs, New Mexico  
September 12, 1961

New Mexico Oil Conservation Commission  
P. O. Box 2045  
Hobbs, New Mexico

Attention: Mr. Eric Engbrecht

Dear Mr. Ingbrecht:


An attempt was made to repair the leak on Tidewater Oil Company's State "S" Well No. 2 by pulling and repacking the PSI side door choke. The repacked choke was rerun into the well, and another packer leakage test was commenced.

Based on this test, we believe that there is still communication between the Blinbry and Tubb gas zones. We have therefore notified the El Paso Natural Gas Company to shut in both zones.

Plans have been submitted to kill the well, pull tubing and packer and repair the faulty equipment.

Yours very truly,

TIDEWATER OIL COMPANY

  
Thomas E. Weaver,  
Area Superintendent

HM:bw

Encl. 2 packer leakage test charts