

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-06624
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name HARRY LEONARD (NCT-E)
8. Well No. 5
9. Pool name or Wildcat DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER	2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator P.O. Box 1150, Midland, TX 79702	4. Well Location Unit Letter H : 2310 Feet From The NORTH Line and 330 Feet From The EAST Line Section 16 Township 21S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: TA'D ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH W/TBG. LOCATED CSG LEAK @ 2850'. CIBP @ 6425' OK. LOCATED CSG LEAK 3928'-3960'. SET CR @ 3860'; SQZD W/75 SX CL "C" 1200#. RVRSD OUT 1 BBL CMT. SPOTTED 25 SX CL "C" @ 2973'. TSTD CSG 500#. TAGGED CMT @ 2705'; DRLD 2705'-3015'. TSTD CSG 300# 15 MIN - OK. DRLD CR & CMT 3860'-3965'. TSTD 300#. BLED TO 0# IN 10 SEC. SET CR @ 3860'. TSTD ANN - HELD OK. ESTAB INJ RATE. SQZD W/150 SX CL "C" 2500#. CIRC 2 BBLS. TAGGED CMT @ 3830'; DRLD 3830'-3860'. DRLD CR & CMT 3860'-3993'. CIRC HOLE CLEAN. TSTD CSG 500# 30 MIN - HELD OK.

TA'D 10/24/97

This Approval of Temporary
Abandonment Expires 3/30/2003

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE TECHNICAL ASSISTANT DATE 3/10/98
TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915)687-7148

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

