

DUPLICATE

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY - 1951

Land Office

Las Cruces

038096 (a)

Unit

RECEIVED
OIL CONSERVATION COMMISSION
MORRIS-OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	1
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 28, 1951

A. M. Lockhart

Well No. 2 is located 940 ft. from $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line and 990 ft. from $\begin{Bmatrix} E \\ W \end{Bmatrix}$ line of sec. 17SW/4 Sec. 17
(1/4 Sec. and Sec. No.)21-3
(Twp.)37E
(Range)NMPM
(Meridian)Drinkard
(Field)Lea
(County or Subdivision)New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 94 joints, 2777' of Spang 7-5/8" H40, 24 lb. 8 rd. thread Casing and Halliburton Float Collar, 29' above a Halliburton Guide shoe, set @ 2788' with 1150 sacks cement 3% gel and 100 sacks neat cement. Cement circulated behind 7-5/8" casing - Job completed 1 AM, October 23, 1951. Found cement inside 7-5/8" casing @ 2755', Tested casing with 1000 lbs. 1 hour with no leak on October 26, 1951. Drilled shoe and tested with 1000 lbs. No leak. Started drilling formation Oct., 26, 1951

ILLEGIBLE

I understand that this plan of work must receive approval in writing by _____ survey before operations may be commenced.

Company DIXIELYN DRILLING COMPANY

Address Box #3427

Odessa, Texas

By

Title

Co-Owner

