

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06646
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name W. W. Weatherly
8. Well No. 3
9. Pool name or Wildcat Tubb Oil & Gas

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Oryx Energy Company
3. Address of Operator P. O. Box 1861, Midland, Texas 79702

4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>17</u> Township <u>21-S</u> Range <u>37-E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, Gn, etc.) 3483' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Stimulate</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/15/91 MIRU X-pert WS.
1/16/91 Wash perfs 6266-6436' w/2% KCL wtr, tag PBSD 6456.
1/17/91 BJ acidize perfs 6266'6436' w/2500 gals 85/15 acid/xylene + 53 tons CO₂ in 3 stages.
1/18/91 Flow. & Swab.
1/19/91 TIH w/2-3/8" prod. tbg and pumping setup, TS 6421', SN 6388', 5-1/2" TAC at 5398' set w/12,000# tension, RIH w/2"x1.5"x12' pump on 76 rod string.
1/20 thru 1/29/91 Pumping.
1/30/91 24P 7 BO 3 BW 124 MCF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maria L. Perez TITLE Proration Analyst DATE 2-1-91

TYPE OR PRINT NAME Maria L. Perez TELEPHONE NO. 915/688-0375

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

FEB 06 1991

1911
Omaha