

OIL CONSERVATION COMMISSION
HOBBS, NEW MEXICO

May 11, 1964

Amerada Petroleum Corporation
Box 668
Hobbs, New Mexico

Re: L. G. Warlick "A" #2-J
Section 19, T21S, R37E
Packer Leakage Test

Gentlemen:

The last packer leakage test upon the above well indicates a decrease in pressure in zone #2 during flow test of zone #1 and zone #4.

We request a retest of this well with this recommended procedure. All parts of the test shall be twenty-four hours long. We recommend that the zones be produced in this order -- Penrose-Skelly, Drinkard, and Paddock -- with Blinbry zone shutin at all times.

Thank you very much for your cooperation in this matter.

Very truly yours,

OIL CONSERVATION COMMISSION

Eric F. Engbrecht
Engineer, District I

EFE:fd

cc: Mr. Joe D. Ramey, Supervisor, District I NMOCC