

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator <b>GRAHAM ROYALTY, LTD</b>	3. Address of Operator <b>5429 LBJ FREEWAY, SUITE 550 DALLAS, TX 75240</b>	4. Location of Well UNIT LETTER <b>A</b> <b>660</b> FEET FROM THE <b>NORTH</b> LINE AND <b>660</b> FEET FROM THE <b>EAST</b> LINE, SECTION <b>19</b> TOWNSHIP <b>21S</b> RANGE <b>37E</b> NMPM.	7. Unit Agreement Name	8. Farm or Lease Name <b>WARLICK QUEEN</b>	9. Well No. <b>1</b>	10. Field and Pool, or Wildcat <b>EUMONT Y-SR-QU</b>	11. Elevation (Show whether DF, RT, CR, etc.) <b>3524' KB</b>	12. County <b>LEA</b>
--	---	---	---	------------------------	---	-------------------------	---	--	--------------------------

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/28/88 MIRU Permian Basin Casing Pullers. POH w/rods and pump. POH w/2 3/8" tbq.

6/30/88 Set 5 1/2" CIBP on 2 3/8" tbq @ 3297' (witnessed and approved by NMOCC). Spot 5 sx cmt on CIBP 3297' - 3253'. Displace hole w/9.5 ppg mud-laden fluid. Spot 20 sx cmt plug thru 2 3/8" tbq 350'-178'. Cut off well head. Spot 3 sx cmt surface plug. Weld on steel plate. Install dry hole marker. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Jack D. Bledsoe</i></u>	TITLE <u>Production Superintendent</u>	DATE <u>7-19-88</u>
APPROVED BY <u><i>R. A. V. Allen</i></u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>AUG 21 1988</u>
CONDITIONS OF APPROVAL, IF ANY:		