



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **032591 (c)**
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Notice of intention to DUAL WELL	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 2nd, 19 58

Well No. **2 Hardy** is located **430** ft. from **N** line and **330** ft. from **E** line of sec. **19**
SE/4 Section 19 **21-S** **38-E** **NMPM**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Drinkard **Lee** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3500** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plan to set production type packer at 6550' and perforate interval 5594' - 5935' in Elinebry Gas Pool. Run removable bridge plug and set same at 6000'. Sand-Fracture Elinebry Zone down 5 1/2" casing with 20,000 gallons oil and 20,000 pounds sand. Place well on production, producing Drinkard Zone through tubing and Elinebry Gas through tubing-casing annulus.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **J. W. PEERY**

Address **P.O. Box 655**

Odessa, Texas

By *[Signature]*

Title **Owner & Operator**