

(SUBMIT IN TRIPLICATE)

Land Office	Santa	ľ,	
Lease No. L	C-03259) 1 -(رع.

UNITED STATES

DEPARTMENT OF THE INTERIOR Unit 5 17

SUNDRY NOTICES	AND REPORTS ON WELLS
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL "IOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY.
(INDICATE ABOVE BY CHE 18.)	MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
	July 15, , 1963
Well No. 4 is located 230 f., f.	rom [E] line and 530 ft. from [E] line of sec. 19
Paddock Ground Level The elevation of the steerick floor above sea	Rew Rexico
DE	TAILS OF WORK
State names of and expected depths to objective sands; sho ing points, and	w sizes, weights, and langths of proposed casings; indicate mudding jobs, cement all other important proposed work)
Acidize Glorietta zone 5160 to 517	0 with 3,500 gailons regular 15% acid.
	umjed 62 (C) jius 3 water on June 21,
1963. COm 1,171 cu. ft. per barr	el.
0 1 4 2000	at in writing by the Geological Survey before operations may be commenced.
Address F. C. Box 401	
4472	
idland	Ву
	Title artner