

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPERF OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator <b>SUN OIL COMPANY</b>		8. Farm or Lease Name <b>J. G. RANDLE</b>
3. Address of Operator <b>P. O. BOX 1861, MIDLAND, TEXAS 79701</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>E</b> <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>20</b> TOWNSHIP <b>21S</b> RANGE <b>37E</b> NMPM.		10. Field and Pool, or Wildcat <b>DRINKARD</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>DF 3519</b>		12. County <b>LEA</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

OTHER **Recomplete in the Blinebry** ☒

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**INTENTION: Shut off Drinkard w/B.P., perf Blinebry and test.**

**MC-1606 authorized dual completion in the Drinkard & Blinebry.**

1. POH w/rods & tbq.
2. GIH w/RBP & pkr on tbq. Set BP @ 6560' & test to 3000#.
3. POH W/pkr & tbq.
4. Log to 6560. Perf Blinebry perfs to be picked after log is run.
5. Acidize Blinebry perfs.
6. POP & test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gray TITLE Proration Analyst DATE 8-31-76  
APPROVED BY Orly Signed by Jerry Sexton TITLE  DATE 8/31/76  
CONDITIONS OF APPROVAL Not a Sign