

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103.
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State	<input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Dual	7. Unit Agreement Name
2. Name of Operator Continental Oil Company	8. Farm or Lease Name M. E. Wantz
3. Address of Operator P. O. Box 460, Hobbs, New Mexico	9. Well No. 8
4. Location of Well UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 21 RANGE 37E NMPM.	10. Field and Pool, or Wildcat Nolan-Wantz-State 10
15. Elevation (Show whether DF, RT, GR, etc.) 3459 DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Abandon Abo, Recomplete Bline. <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The M. E. Wantz No. 8 was initially completed in the Ellenburger at a total depth of 8072 on October 21, 1948 for an IP of 1468 BO, no water with GOR of 600.

On 6-19-59 the well was dual completed in Abo and Blinebry Pay. Presently the Abo Zone pumps 8 BO and 25 BW. The Blinebry Zone is shut in due to over production.

In order to eliminate uneconomical remedial work and to maintain production from the Blinebry Zone, it is recommended to abandon the Abo zone rather than replace tubing string which has a leak and must be replaced.

It is proposed to kill well w/oil, pull tubing, dump sand down casing on top of packer. Place 2 sacks cement on top. Run tubing and swab in Blinebry.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **HAL R. STEPHENS** TITLE **Staff Supervisor** DATE **2-1-66**

NMOCC-5 File

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: