CRSY AND MINERALS DEPARTME	INT		
er Chaice percines	CONSERVA	TION DIVISION	•
DISTRIBUTION			
IANTA PE	. SANTA FE, NEW	MEXICO 87501	Revised 10-1-
FILE	1		5a. Indicate Type of Lease
v.s.a.s.	4	•	State Fee X
LAND OFFICE			5, State Oli 6 Gas Lease No.
OPERATOR	J		St prote ()II & Ous Ladge No.
Pulp FARLI FAR PM	RY NOTICES AND REPORTS ON	ACH TO A DIFFERENT RESERVAGE	
on X GAS WELL	OTME#+		7. Unit Agreement Name
line of Operator			8. Farm or Lease Itame
Alpha Twenty-One Production Company			Mary Wantz
adrass of (perator			9. Well No.
P.O. Box 1206 Jal, New Mexico 88252			2
scatton of Well			10. Field and Pool, or Wildcat
L I	1980 FEET FROM THE South	LINE AND FEET PA	Eumont Queen
West LINE, SECTION	21 21 S		
15. Elevation (Show whether DF, RT, GR, etc.)			12. County Lea
	Appropriate Box To Indicate N NTENTION TO:	· · · · · · · · · · · · · · · · · · ·	Other Data NT REPORT OF:
FORM REMEDIAL WORK PORARILY ABANDON OF ALTER CASING	PLUG AND ABANDON X	REMEDIAL WORK COMMENCE DRILLING OPNS. CABING TEST AND CEMENT JQS OTHER	ALTERING CABING PLUG AND ABANDONMENT
A SHIP			
Describe Proposed or Completed Opuple) SEE RULE 1703.	perations (Clearly state all pertinent deta	sils, and give pertinent dates, includ	ing estimated date of starting any proposi
Plugging Procedure	·•		-
riugging frocedure	2∙		•
1. CIBP set at 3	3150' with 35' of cement	on top of CTRP	
	from 2600'-2400'. (200')		
	1375; set retainer at 1		GKS DETOM
	5 sacks on top of retain		1 7 Ar • \
In cack mind	from $2601-1101$ (751 in	and the out agains sho	A 94 IX5II

- 15 sack plug from 260'-110' 10 sack plug at surface.

No casing will be pulled.

10-3/4" casing set at 185' 5-1/2" casing set at 3213' Open hole from 3215'-3775'.					
nereby certify that the information above is true and c		edge end belief. Superintendent	DATE_	8-22-84	
Eddie W. Seay	TITLE		DATE_	AUG 28 198	4
DITIONS OF APPROVAL, IF ANYI			·		

RECEIVED

AUG 2 3 1984

O.C.D. HOBBS OFFICE