

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL OTHER: Dual Completion - Blinebry & Tubb

2. Name of Operator
N. B. Hunt

3. Address of Operator
406 N. Big Spring Midland, Texas 79701

4. Location of Well
UNIT LETTER G 1980 FEET FROM THE East LINE AND 2,090' FEET FROM
THE North LINE, SECTION 21 TOWNSHIP 21S RANGE 37E N.M.P.M.

5. Elevation (Show whether DF, RT, GR, etc.)
3,462' GR

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name
Mittie Weatherly

9. Well No.
1

10. Field and Pool, or Wildcat
Eunice Drinkard

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This workover is scheduled to begin within the next month, if we receive your approval. The following is a step-by-step procedure of the proposed workover.

- 1.) Log the Tubb, Blinebry, Glorietta, San Andres, Queens & Grayburg with CBL, GR-CNL, & TDT.
- 2.) Perforate the Tubb as logs indicate.
- 3.) Acidize Tubb with 2,000 gallons of 15% HCl.
- 4.) Flow and/or swab back load & test.
- 5.) Perforate the Blinebry as logs indicate.
- 6.) Frac the Blinebry with 27,000 gallons of gelled water with 39,000 lbs. of 20/40 sand.
- 7.) Flow and/or swab back load & test.
- 8.) Place well back on production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: [Signature] TITLE: Petroleum Engineer DATE: 1-20-83

APPROVED BY: ORIGINAL SIGNED BY TITLE: DATE: JAN 25 1983
EDDIE W. SEAY

RECEIVED

JAN 24 1983

O.C.D.
HIGGS OFFICE

100-100000
100-100000