

Submit 3 Copies
to Appropriate
District Office

2

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

Form C-103
Revised 1-1-89

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)	30-025-06733
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	N/A
7. Lease Name or Unit Agreement Name	EUEANK
8. Well No.	7
9. Pool name or Wildcat	DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	
4. Well Location Unit Letter <u>B</u> : <u>450</u> Feet From The <u>NORTH</u> Line and <u>2306</u> Feet From The <u>EAST</u> Line Section <u>22</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3424' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTER CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO PLUG AND ABANDON THIS WELLBORE AS FOLLOWS:
(TD @ 7630', 7" CASING @ 7629, 9-5/8" CASING @ 2799', 13-3/8" CASING @ 306')
ND WH, NU BOP, CUT 9-5/8" CASING @ 300' & PULL. CUT 7" CASING @ 2750' & PULL.
PLACE 20 SX PLUG 6180-6300, ABOVE DRINKARD PERFS @ 6392-6618'. PLACE 35 SX
PLUG FROM 5000-5200', PLACD 35 SX PLUG 2500-2700'. PLACE 150 SX PLUG 200-400'
AND TAG. PLACE 100 SACK SURFACE PLUG FROM 150' TO SURFACE.
PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION
PLACE P&A MARKER AND CHANGE STATUS OF WELL TO PLUGGED AND ABANDONED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	<u>Nita Rice</u>	TITLE	TECHNICAL ASSISTANT
DATE:		3/4/93	
TYPE OR PRINT NAME		NITA RICE	
TELEPHONE NO. (915)687-7436			
APPROVED BY		DATE	
Paul Kautz		MAR 30 1993	
CONDITIONS OF APPROVAL, IF ANY:			

THE OIL CONSERVATION DIVISION
RECEIVED THIS NOTICE OF INTENTION
TO PLUG AND ABANDON THE WELL
ON 3/4/93