

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ For ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name ARGO "A"
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 5
4. Location of Well UNIT LETTER F, 2130 FEET FROM THE WEST LINE AND 1980 FEET FROM THE NORTH LINE, SECTION 22 TOWNSHIP 21-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat BLINEBRY OIL AND GAS
15. Elevation (Show whether DF, RT, GR, etc.) 3427' DF	12. County LEA

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER OPEN ADDITIONAL PAY AND ACIDIZE <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-26-82: Unseated AR-1 packer @ 5341'.
4-27-82: Stung out of Model D packer @ 5880'. Set RBP @ 5950' and pkr @ 5870'.
4-28-82: Acidized perms 5892' - 5937' w/3,000 gals 15% NEA. Set RBP @ 5870'; pkr @ 5650'.
Acidized perms 5703' - 5862' w/5,400 gals 15% NEA. Set RBP @ 5650'; pkr @ 5420'.
Acidized perms 5498' - 5628' w/6,600 gals 15% NEA.
5-05-82: Installed production equipment and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Louis Curtis for A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE AUGUST 24, 1982

APPROVED BY _____ TITLE _____ DATE AUG 30 1982

CONDITIONS OF APPROVAL, IF ANY: