STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES ACCEIVED	T	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		L_
OPERATOR		

OIL CONSERVATION DIVISION

NO. OF COPIED RECEIVED	OIL CONSERVA	TION DIVISION	
DISTRIBUTION	* P. O. BO	C 2088	Form C-103 Revised 10-1-78
SANTA FE	SANTA FE, NEW	MEXICO 87501	
FILE			Sa. Indicate Type of Lease
U.S.O.S.		·	State Fee X
LAND OFFICE			5. State Oil 6 Gas Lease No.
OPERATOR	•		J. state on a dead grant train
			-
SUNDRY (DO NOT USE THIS FORM FOR PROPERTY USE "MAPPLICATION")	NOTICES AND REPORTS ON OSALS TO DRILL OR TO DEEPEN OF PLUG SON FOR PERMIT - " (FORM C-101) FOR SUC	WELLS ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)	
1.			7. Unit Agreement Name
WELL XX WELL	OTHER*		
2. Name of Operator			8, Farm or Lease Name
		•	TURNER
SHELL OIL COMPANY			9. Well No.
3. Address of Operator			7.5
P. O. BOX 991, HOUSTO	N, IX //001		15 10. Fletd and Pool, or Wildcat
4. Location of Well			I HOLNKADH I
UNIT LETTER O	90 FEET FROM THE SOUTH	LINE AND 2310 PEET PROP	BLINEBRY OIL AND GAS
EAST	N 22 TOWNSHIP 21-5	S RANGE 37-E NMPM	
THE LINE, SECTIO	10743417		
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	3416' DF		LEA ())))))
Check A	appropriate Box To Indicate N		
NOTICE OF IN	TENTION TO:	SUBSEQUEN	T REPORT OF:
•			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
	CHANGE PLANS	CASING TEST AND CEMENT JOB	
PULL OR ALTER CASING		OTHER	
ODEN ADDITIONAL DA	Y IN DRINKARD ZONE; X	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
DOWNHOLE COMMINGLE W	/PLINERDV *		
DUMNITULE COMPLETED OF	erations (Clearly state all pertinent deta	ails, and give pertinent dates, includin	g estimated date of starting any proposed
work) SEF RULE 1603.			·

ne information above is true and comple L. S.O.NED BY JERRY SEXTON	te to the best of my ki			DATE MARCH 3	31, 1983
7 -1				MARCH 3	31 . 1983
ie information above is true and comple	te to the beat of my kr	lowledge and bei	elief.		
		•			
	·	·			
		·			
					•
ommingred birnesiy-birne	turu tuping so	,g p.			
ommingled Blinebry-Drink	ard tubing st				
		rina to pr	roduction.		•
	ommingled Blinebry-Drink	onmittigled bittlesig si tindia basing so			omming to a 2.7 mostly 2.7 man a call might be presented as