

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name TURNER
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 16
4. Location of Well UNIT LETTER M 330 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 22 TOWNSHIP 21-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat BRINKARD <i>Farre</i>
15. Elevation (Show whether DF, RT, GR, etc.) 3427' DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☒

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

1. Set CIBP @ 3950' and cap w/  $\pm$  35' of cement. Circulate hole w/inhibited water.
2. Leave pressure gauge in well head to monitor casing pressure.
3. Temporarily abandon well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *A. J. Fore* A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JULY 28, 1982

APPROVED BY JERRY SEXTON TITLE DATE AUG 2 - 1982

CONDITIONS OF APPROVAL, IF ANY: