Submit 5 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

CONDITIONS OF APPROVAL, IF ANY:

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	WELL API NO.
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brizzos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
/ DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	NORTHEAST DRINKARD UNIT
1. Type of Well: OIL OAS WELL WELL OTHER	NONTHENST DISTRICTION OF THE
2. Name of Operator	8. Well No. 912
SHELL WESTERN E&P INC. 3. Address of Operator	
P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9 Post pame or Wildest NORTH - EUNICE BLINEBRY - TUBB -
4. Well Location	DRINKARD OIL & GAS
Unit Letter M: 660 Feet From The SOUTH Line and 660	Feet From TheWEST Line
	NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	. \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
3391 GR	aport or Other Data
Check Appropriate Box to Indicate Nature of Notice, R NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
NOTICE OF INTENTION TO.	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CE	EMENT JOB
OTHER: CMT	SOZ; OAP; AT.
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu	ding eximated date of starting any proposed
work) SEE RULE 1103.	
3-22-89 TO 4-10-89	
POH WITH TBG & MODEL "M" PKR. RIH WITH MODEL "D" PLUG & S	FT @ 6290'. & CAP WITH
3 SX SAND. RIH WITH PKR & SET @ 5894'. ESTABLISHED INJ RA	TE. POH WITH PKR. RIH
WITH CICR & SET @ 5865'. SQZD TUBB (5960-6200') WITH 250	
OUT CICR & CMT TO 6245'. CIRC'D SAND OFF PLUG. RIH WITH P TO 600#, HELD. POH WITH PKR. POH WITH MODEL "D" PLUG. DR	
PERFED BLINEBRY/TUBB/DRINKARD (5688-6582') WITH 1 JSPF.	
RBP @ 6590', PKR @ 6525'. ACD WITH 710 GAL 15% ACID. RESE	T PKR @ 6250'. ACD WITH
4200 GAL 15% ACID. POH WITH PKR. RIH WITH RBP #2 & SET @	
ACID. RIH WITH PKR & SET @ 5910'. PUMPED 10 BBLS ACID. RE 5850'. ACD WITH 840 GAL 15% ACID. RESET PKR @ 5600'. ACD	· · · · · · · · · · · · · · · · · · ·
· ·	WITH SISS UME 13% NOTE.
I hereby certify that the information above is true and complete to the dest of my knowledge and belief. SERVICE THE PROD. ADMIN.	ADVISOR 5-17-89
SKINATURE	
TYPEORPRINT NAME J. H. SMITHERMAN (7)	13) 870–3797 телерионе но.
(This space for State Up) ORIGINAL SIGNED BY JERRY SEXTON	MAY 2 2 1989
DISTRICT I SUPERVISOR	MAI & & 1989
APPROVED BYTITLE	

TEMPORARILY ABANDON PULL OR ALTER CASING

11.

OTHER:

E

Submit 3 Copies	State of Nev	w Mexico	Form C-103
to Appropriate District Office	Energy, Minerals and Natur	al Resources Department	Revised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVAT		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mex	rico 87504-2088	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	-		6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVED.)	ICES AND REPORTS ON 1 DPOSALS TO DRILL OR TO DEE RVOIR. USE "APPLICATION FOR -101) FOR SUCH PROPOSALS.)	PEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
1. Type of Well: OIL GAS WELL XX WELL [OTHER		
 Name of Operator SHELL WESTERN E&P IN 	IC.		8. Well No. 912
3. Address of Operator P. O. BOX 576, HOUST		K 4435)	9 Pool name of Wildert NORTH EUNICE BLINEBRY-TUBB-
4. Well Location Unit Letter M: 660	Feet From The SOUTH	Line and 660	DRINKARD OIL & GAS Description The WEST Line
Section 23	Township 21S	Range 37E	NMPM LEA County
	3391' GR	ether DF, RKB, RT, GR, etc.)	·
11. Check A NOTICE OF INT	Appropriate Box to Indicate Tention TO:		Report, or Other Data SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	_	CASING TEST AND C	
OTHER:		OTHER:	CMT SQZ; OAP; AT X
 Describe Proposed or Completed Operat work) SEE RULE 1103. 	ions (Clearly state all pertinent detail	ls, and give pertinent dates, inclu	iding estimated date of starting any proposed
CONT'D			
RESET RBP @ 6090', P POH WITH RBP @ 6590'	KR @ 5910'. ACD WITH . RIH WITH PROD EQUI	I 1050 GAL 15% HCL P. RETD TO PROD.	. POH WITH PKR & RBP #2.
			•

I hereby certify that the information above is true and complete to the best of my knowles	dge and belief.	
SKINATURE Affantheman	TITLE PROD. ADMIN. ADVISOR DATE 5-17-89	
TYPE OR PRINT NAME J. H. SMITHERMAN	(713) 870–3797 тецерноме но.	
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	MAY 2 2 198	9
APPROVED B I	THE DATE	