

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-06760

5. Indicate Type of Lease
FED ☐ STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101 FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

NORTHEAST DRINKARD UNIT

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

SHELL WESTERN E&P INC.

8. Well No. 911

3. Address of Operator

P. O. BOX 1950, HOBBS, NM 88240 505/393-0325

9. Pool name or Wildcat

N. EUNICE BLINEBRY-TUBB-DRINKARD

4. Well Location

Unit Letter L : 1980 Feet From The SOUTH Line and 660 Feet From The WEST Line
Section 23 Township 21-S Range 37-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT GR, etc.)
3411 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: CO & Stimulate ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Clean out and stimulate Lower Blinebry and Drinkard.
2) Return to Production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. L. Mann

TITLE PRODUCTION FOREMAN

DATE 10/3/95

TYPE OR PRINT NAME C. L. MANN

TELEPHONE NO. 505/393-0209

APPROVED BY

TITLE

DATE

OCT 03 1995

COMPLETION OF APPROVAL BY ANY:

