	SAN [®]			FORM C-110 (Rev. 7-60) C.
онниатон		OPIES WITH THE	APPROPRIATE OFFN	Well No.
Unit Letter Section Township	Fange	•••	County	4
N 23 21 S	!	37 E	Lea Lind of Lease (State, Fed.	(Free)
Blinebry	nin and states - 10 and 1000 - 1000 and	J';	and of Lease (State, Fea,	Fee
If well produces oil or condensate give location of tanks	nit Letter K	Section 23	Township 21 S	Range 37 E
Authorized transporter of oil 🛒 or condensate				y of this form is to be sent)
Shell Pipe Line Corporation		Box 159	98 Hobbs, N	ew Mexico
	ally Connecte	d? Yes1	Vo	
Authorized transporter of casing head gas χ or dry gas []	Date Con- nected	Address (give address to which approved copy of this form is to be sent)		
Skelly Oil Company	2 1964	Box 114 Eunice, New Mexico		
Change in Transporter (check one) Oil Dry Gas Casing head gas Condens		Other (explain bei Recompleted February 19	from Drinkard t	o Blinebry
Remark s				
he undersigned certifies that the Rules and Regulation	s of the Oil Co	nservation Commi	ssion have been complie	ed with.
	as of the Oil Con		ssion have been complie _ , 19 _ 64 .	ed with.
		By	_ , 19_ 64 .	ed with.
Executed this the 20th data data data data data data data dat		By S. B. D	_ , 19_ 64 .	ed with.
Executed this the 20th data data data data data data data dat		By S. B. D Title	_ , 19_ 64 .	Q.S.
		By By Title Division Company	_, 19_ 64 .	Q.S.

-