

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILL	
U.S.G.S	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

(Form C-102)
(Revised 7/1/62)

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBBS OFFICE P. O. C.

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Roswell, New Mexico

January 15, 1964

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Shell Oil Company

Sarkeys

Well No. 4

N

(Company or Operator) SE 1/4 SW 1/4 of Sec. 23, T. 21 S, R. 37 E, NMPM, Drinkard (Unit) Pool

Lea

County.

RECOMPLETE FROM DRINKARD TO BLINEBRY

FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

1. Pull tubing. Set CIBP at 6375' and cap with cement.
2. Run GR/N w/CCL survey from PBSD to 2900'.
3. Perforate Blinebry intervals between 5700' and 5860'.
4. Run 3" x-line tubing with FBRC. Acidize perforations with 1500 gallons 15% NE acid using ball sealers.
5. Fracture treat with 20,000 gallons lease crude containing 1# 20-40 mesh radioactive sand per gallon plus 1/20# Mark II Adomite per gallon.
6. Run production equipment and swab test.
7. Place on production.

Approved....., 19.....
Except as follows:

Shell Oil Company

R. A. Lowery

Original Signed By
R. A. LOWERY

By.....

Position..... District Exploitation Engineer

Send Communications regarding well to:

Shell Oil Company

Name.....

Box 1858

Roswell, New Mexico

Address.....

Approved
OIL CONSERVATION COMMISSION

By.....

Title.....